

M track length table

the number of some tracks has been limited because:

- 2*5208 is suppressed in favor of 5210
- 2*5110 is suppressed in favor of 5108
- 2*5108 is suppressed in favor of 5107
- 2*5107 is suppressed in favor of 5106
- 9*5129 is suppressed in favor of 7*5107
- 7*5210 is suppressed in favor of 5108 + 2*5109
- 6*5109 is suppressed in favor of 2*5129 + 5108 + 5210

where possible, 5208 is avoided

all combinations shown up to length 720.00 mm

only one best combination per millimeter shown for longer lengths

.....	1*5208	(1) =	8.00		
.....	1*5210	(1) =	16.00		
.....	1*5110	(1) =	22.50		
.....	1*5210	1*5208	(2) =	24.00	
.....	1*5110	1*5208	(2) =	30.50
.....	2*5210	(2) =	32.00
.....	1*5109	(1) =	33.50
.....	1*5110	1*5210	(2) =	38.50
.....	2*5210	1*5208	(3) =	40.00
.....	1*5109	1*5208	(2) =	41.50
.....	1*5108	(1) =	45.00
.....	1*5110	1*5210	1*5208	(3) =	46.50
.....	3*5210	(3) =	48.00
.....	1*5109	1*5210	(2) =	49.50
.....	1*5108	1*5208	(2) =	53.00
.....	1*5110	2*5210	(3) =	54.50
.....	1*5109	1*5110	(2) =	56.00
.....	1*5109	1*5210	1*5208	(3) =	57.50
.....	1*5108	1*5210	(2) =	61.00
.....	1*5110	2*5210	1*5208	(4) =	62.50
.....	4*5210	(4) =	64.00
.....	1*5109	1*5110	1*5208	(3) =	64.00
.....	1*5109	2*5210	(3) =	65.50
.....	2*5109	(2) =	67.00
.....	1*5108	1*5110	(2) =	67.50
.....	1*5108	1*5210	1*5208	(3) =	69.00
.....	1*5129	(1) =	70.00
.....	1*5110	3*5210	(4) =	70.50
.....	1*5109	1*5110	1*5210	(3) =	72.00
.....	1*5109	2*5210	1*5208	(4) =	73.50
.....	2*5109	1*5208	(3) =	75.00
.....	1*5108	1*5110	1*5208	(3) =	75.50
.....	1*5108	2*5210	(3) =	77.00
.....	1*5129	1*5208	(2) =	78.00
.....	1*5108	1*5109	(2) =	78.50
.....	5*5210	(5) =	80.00
.....	1*5109	1*5110	1*5210	1*5208	(4) =	80.00
.....	1*5109	3*5210	(4) =	81.50
.....	2*5109	1*5210	(3) =	83.00
.....	1*5108	1*5110	1*5210	(3) =	83.50
.....	1*5108	2*5210	1*5208	(4) =	85.00
.....	1*5129	1*5210	(2) =	86.00
.....	1*5110	4*5210	(5) =	86.50
.....	1*5108	1*5109	1*5208	(3) =	86.50
.....	1*5109	1*5110	2*5210	(4) =	88.00
.....	2*5109	1*5110	(3) =	89.50
.....	1*5107	(1) =	90.00
.....	1*5210	1*5208	(4) =	91.00
.....	1*5108	1*5110	1*5210	1*5208	(4) =	91.50
.....	1*5129	1*5110	(2) =	92.50
.....	1*5108	3*5210	(4) =	93.00
.....	1*5129	1*5210	1*5208	(3) =	94.00
.....	1*5108	1*5109	1*5210	(3) =	94.50
.....	6*5210	(6) =	96.00
.....	1*5109	1*5110	2*5210	1*5208	(5) =	96.00
.....	1*5109	4*5210	(5) =	97.50
.....	2*5109	1*5110	1*5208	(4) =	97.50
.....	1*5107	1*5208	(2) =	98.00
.....	2*5210	(4) =	99.00
.....	1*5108	1*5110	2*5210	(4) =	99.50
.....	3*5109	(3) =	100.50
.....	1*5108	1*5109	1*5110	(3) =	101.00
.....	1*5129	2*5210	(3) =	102.00
.....	1*5110	5*5210	(6) =	102.50
.....	1*5108	1*5109	1*5210	1*5208	(4) =	102.50
.....	1*5129	1*5109	(2) =	103.50
.....	1*5109	1*5110	3*5210	(5) =	104.00
.....	2*5109	1*5110	1*5210	(4) =	105.50
.....	1*5107	1*5210	(2) =	106.00
.....	2*5109	2*5210	1*5208	(5) =	107.00
.....	1*5108	1*5110	2*5210	1*5208	(5) =	107.50

M track length table

.....	1*5129	1*5110	1*5210	(3) =	108.50
.....	1*5108	4*5210	(5) =	109.00
.....	1*5108	1*5109	1*5110	1*5208	(4) =	109.00
.....	1*5129	2*5210	1*5208	(4) =	110.00
.....	1*5108	1*5109	2*5210	(4) =	110.50
.....	1*5129	1*5109	1*5208	(3) =	111.50
.....	1*5108	2*5109	(3) =	112.00
.....	1*5107	1*5110	(2) =	112.50
.....	1*5109	5*5210	(6) =	113.50
.....	2*5109	1*5110	1*5210	1*5208	(5) =	113.50
.....	1*5107	1*5210	1*5208	(3) =	114.00
.....	1*5129	1*5108	(2) =	115.00
.....	1*5108	1*5110	3*5210	(5) =	115.50
.....	3*5109	1*5210	(4) =	116.50
.....	1*5108	1*5109	1*5110	1*5210	(4) =	117.00
.....	1*5129	3*5210	(4) =	118.00
.....	1*5110	6*5210	(7) =	118.50
.....	1*5108	1*5109	2*5210	1*5208	(5) =	118.50
.....	1*5129	1*5109	1*5210	(3) =	119.50
.....	1*5109	1*5110	4*5210	(6) =	120.00
.....	1*5108	2*5109	1*5208	(4) =	120.00
.....	1*5107	1*5110	1*5208	(3) =	120.50
.....	2*5109	1*5110	2*5210	(5) =	121.50
.....	1*5107	2*5210	(3) =	122.00
.....	1*5129	1*5108	1*5208	(3) =	123.00
.....	3*5109	1*5110	(4) =	123.00
.....	1*5107	1*5109	(2) =	123.50
.....	1*5129	1*5110	2*5210	(4) =	124.50
.....	1*5108	5*5210	(6) =	125.00
.....	1*5108	1*5109	1*5110	1*5210	1*5208	(5) =	125.00
.....	1*5129	1*5109	1*5110	(3) =	126.00
.....	1*5108	1*5109	3*5210	(5) =	126.50
.....	1*5129	1*5109	1*5210	1*5208	(4) =	127.50
.....	1*5108	2*5109	1*5210	(4) =	128.00
.....	1*5107	1*5110	1*5210	(3) =	128.50
.....	2*5109	1*5110	2*5210	1*5208	(6) =	129.50
.....	1*5109	6*5210	(7) =	129.50
.....	1*5107	2*5210	1*5208	(4) =	130.00
.....	1*5129	1*5108	1*5210	(3) =	131.00
.....	1*5108	1*5110	4*5210	(6) =	131.50
.....	1*5107	1*5109	1*5208	(3) =	131.50
.....	3*5109	2*5210	(5) =	132.50
.....	1*5108	1*5109	1*5110	2*5210	(5) =	133.00
.....	4*5109	(4) =	134.00
.....	1*5108	2*5109	1*5110	(4) =	134.50
.....	1*5107	1*5108	(2) =	135.00
.....	1*5129	1*5109	2*5210	(4) =	135.50
.....	1*5109	1*5110	5*5210	(7) =	136.00
.....	1*5108	2*5109	1*5210	1*5208	(5) =	136.00
.....	1*5107	1*5110	1*5210	1*5208	(4) =	136.50
.....	1*5129	2*5109	(3) =	137.00
.....	1*5129	1*5108	1*5110	(3) =	137.50
.....	1*5107	3*5210	(4) =	138.00
.....	1*5129	1*5108	1*5210	1*5208	(4) =	139.00
.....	3*5109	1*5110	1*5210	(5) =	139.00
.....	1*5107	1*5109	1*5210	(3) =	139.50
.....	2*5129	(2) =	140.00
.....	1*5129	1*5110	3*5210	(5) =	140.50
.....	1*5108	6*5210	(7) =	141.00
.....	1*5108	1*5109	1*5110	2*5210	1*5208	(6) =	141.00
.....	1*5129	1*5109	1*5110	1*5210	(4) =	142.00
.....	1*5108	1*5109	4*5210	(6) =	142.50
.....	1*5108	2*5109	1*5110	1*5208	(5) =	142.50
.....	1*5107	1*5108	1*5208	(3) =	143.00
.....	1*5129	1*5109	2*5210	1*5208	(5) =	143.50
.....	1*5108	2*5109	2*5210	(5) =	144.00
.....	1*5107	1*5110	2*5210	(4) =	144.50
.....	1*5129	2*5109	1*5208	(4) =	145.00
.....	1*5108	3*5109	(4) =	145.50
.....	1*5107	1*5109	1*5110	(3) =	146.00
.....	1*5129	1*5108	2*5210	(4) =	147.00
.....	1*5108	1*5110	5*5210	(7) =	147.50
.....	1*5107	1*5109	1*5210	1*5208	(4) =	147.50
.....	2*5129	1*5208	(3) =	148.00
.....	1*5129	1*5108	1*5109	(3) =	148.50
.....	1*5108	1*5109	1*5110	3*5210	(6) =	149.00
.....	4*5109	1*5210	(5) =	150.00
.....	1*5108	2*5109	1*5110	1*5210	(5) =	150.50
.....	1*5107	1*5108	1*5210	(3) =	151.00
.....	1*5129	1*5109	3*5210	(5) =	151.50
.....	1*5109	1*5110	6*5210	(8) =	152.00
.....	1*5108	2*5109	2*5210	1*5208	(6) =	152.00
.....	1*5107	1*5110	2*5210	1*5208	(5) =	152.50

M track length table

.....	1*5129	2*5109	1*5210	(4) =	153.00
.....	1*5129	1*5108	1*5110	1*5210	(4) =	153.50
.....	1*5107	4*5210	(5) =	154.00
.....	1*5107	1*5109	1*5110	1*5208	(4) =	154.00
.....	1*5129	1*5108	2*5210	1*5208	(5) =	155.00
.....	3*5109	1*5110	2*5210	(6) =	155.00
.....	1*5107	1*5109	2*5210	(4) =	155.50
.....	2*5129	1*5210	(3) =	156.00
.....	1*5129	1*5108	1*5109	1*5208	(4) =	156.50
.....	4*5109	1*5110	(5) =	156.50
.....	1*5107	2*5109	(3) =	157.00
.....	1*5107	1*5108	1*5110	(3) =	157.50
.....	1*5129	1*5109	1*5110	2*5210	(5) =	158.00
.....	1*5108	1*5109	5*5210	(7) =	158.50
.....	1*5108	2*5109	1*5110	1*5210	1*5208	(6) =	158.50
.....	1*5107	1*5108	1*5210	1*5208	(4) =	159.00
.....	1*5129	2*5109	1*5110	(4) =	159.50
.....	1*5107	1*5129	(2) =	160.00
.....	1*5107	1*5110	3*5210	(5) =	160.50
.....	1*5129	2*5109	1*5210	1*5208	(5) =	161.00
.....	1*5108	3*5109	1*5210	(5) =	161.50
.....	1*5107	1*5109	1*5110	1*5210	(4) =	162.00
.....	2*5129	1*5110	(3) =	162.50
.....	1*5129	1*5108	3*5210	(5) =	163.00
.....	1*5107	1*5109	2*5210	1*5208	(5) =	163.50
.....	1*5108	1*5110	6*5210	(8) =	163.50
.....	2*5129	1*5210	1*5208	(4) =	164.00
.....	1*5129	1*5108	1*5109	1*5210	(4) =	164.50
.....	1*5108	1*5109	1*5110	4*5210	(7) =	165.00
.....	1*5107	2*5109	1*5208	(4) =	165.00
.....	1*5107	1*5108	1*5110	1*5208	(4) =	165.50
.....	4*5109	2*5210	(6) =	166.00
.....	1*5108	2*5109	1*5110	2*5210	(6) =	166.50
.....	1*5107	1*5108	2*5210	(4) =	167.00
.....	5*5109	(5) =	167.50
.....	1*5107	1*5129	1*5208	(3) =	168.00
.....	1*5108	3*5109	1*5110	(5) =	168.00
.....	1*5107	1*5108	1*5109	(3) =	168.50
.....	1*5129	2*5109	2*5210	(5) =	169.00
.....	1*5129	1*5108	1*5110	2*5210	(5) =	169.50
.....	1*5107	5*5210	(6) =	170.00
.....	1*5107	1*5109	1*5110	1*5210	1*5208	(5) =	170.00
.....	1*5129	3*5109	(4) =	170.50
.....	1*5129	1*5108	1*5109	1*5110	(4) =	171.00
.....	1*5107	1*5109	3*5210	(5) =	171.50
.....	2*5129	2*5210	(4) =	172.00
.....	1*5129	1*5108	1*5109	1*5210	1*5208	(5) =	172.50
.....	4*5109	1*5110	1*5210	(6) =	172.50
.....	1*5107	2*5109	1*5210	(4) =	173.00
.....	2*5129	1*5109	(3) =	173.50
.....	1*5129	1*5109	1*5110	3*5210	(6) =	174.00
.....	1*5108	2*5109	1*5110	2*5210	1*5208	(7) =	174.50
.....	1*5108	1*5109	6*5210	(8) =	174.50
.....	1*5107	1*5108	2*5210	1*5208	(5) =	175.00
.....	1*5129	2*5109	1*5110	1*5210	(5) =	175.50
.....	1*5107	1*5129	1*5210	(3) =	176.00
.....	1*5107	1*5110	4*5210	(6) =	176.50
.....	1*5107	1*5108	1*5109	1*5208	(4) =	176.50
.....	1*5129	2*5109	2*5210	1*5208	(6) =	177.00
.....	1*5108	3*5109	2*5210	(6) =	177.50
.....	1*5107	1*5109	1*5110	2*5210	(5) =	178.00
.....	2*5129	1*5110	1*5210	(4) =	178.50
.....	1*5108	4*5109	(5) =	179.00
.....	1*5107	2*5109	1*5110	(4) =	179.50
1*5106	(1) =	180.00
.....	1*5129	1*5108	1*5109	2*5210	(5) =	180.50
.....	1*5108	1*5109	1*5110	5*5210	(8) =	181.00
.....	1*5107	2*5109	1*5210	1*5208	(5) =	181.00
.....	2*5129	1*5109	1*5208	(4) =	181.50
.....	1*5129	1*5108	2*5109	(4) =	182.00
.....	1*5107	1*5129	1*5110	(3) =	182.50
.....	1*5107	1*5108	3*5210	(5) =	183.00
.....	5*5109	1*5210	(6) =	183.50
.....	1*5107	1*5129	1*5210	1*5208	(4) =	184.00
.....	1*5108	3*5109	1*5110	1*5210	(6) =	184.00
.....	1*5107	1*5108	1*5109	1*5210	(4) =	184.50
.....	2*5129	1*5108	(3) =	185.00
.....	1*5129	1*5108	1*5110	3*5210	(6) =	185.50
.....	1*5107	6*5210	(7) =	186.00
.....	1*5107	1*5109	1*5110	2*5210	1*5208	(6) =	186.00
.....	1*5129	3*5109	1*5210	(5) =	186.50
.....	1*5129	1*5108	1*5109	1*5110	1*5210	(5) =	187.00
.....	1*5107	1*5109	4*5210	(6) =	187.50

M track length table

.....	1*5107	2*5109	1*5110	1*5208	(5) =	187.50
1*5106	1*5208	(2) =	188.00
.....	2*5129	3*5210	(5) =	188.00
.....	1*5129	1*5108	1*5109	2*5210	1*5208	(6) =	188.50
.....	4*5109	1*5110	2*5210	(7) =	188.50
.....	1*5107	2*5109	2*5210	(5) =	189.00
.....	2*5129	1*5109	1*5210	(4) =	189.50
.....	1*5129	1*5108	2*5109	1*5208	(5) =	190.00
.....	5*5109	1*5110	(6) =	190.00
.....	1*5107	3*5109	(4) =	190.50
.....	1*5107	1*5108	1*5109	1*5110	(4) =	191.00
.....	1*5129	2*5109	1*5110	2*5210	(6) =	191.50
.....	1*5107	1*5129	2*5210	(4) =	192.00
.....	1*5107	1*5110	5*5210	(7) =	192.50
.....	1*5107	1*5108	1*5109	1*5210	1*5208	(5) =	192.50
.....	2*5129	1*5108	1*5208	(4) =	193.00
.....	1*5129	3*5109	1*5110	(5) =	193.00
.....	1*5107	1*5129	1*5109	(3) =	193.50
.....	1*5107	1*5109	1*5110	3*5210	(6) =	194.00
.....	2*5129	1*5110	2*5210	(5) =	194.50
.....	1*5108	4*5109	1*5210	(6) =	195.00
.....	1*5107	2*5109	1*5110	1*5210	(5) =	195.50
1*5106	1*5210	(2) =	196.00
.....	1*5129	1*5108	1*5109	3*5210	(6) =	196.50
.....	1*5107	2*5109	2*5210	1*5208	(6) =	197.00
.....	1*5108	1*5109	1*5110	6*5210	(9) =	197.00
.....	2*5129	1*5109	1*5210	1*5208	(5) =	197.50
.....	1*5129	1*5108	2*5109	1*5210	(5) =	198.00
.....	1*5107	1*5129	1*5110	1*5210	(4) =	198.50
.....	1*5107	1*5108	1*5109	1*5110	1*5208	(5) =	199.00
.....	1*5107	1*5108	4*5210	(6) =	199.00
.....	5*5109	2*5210	(7) =	199.50
.....	1*5107	1*5129	2*5210	1*5208	(5) =	200.00
.....	1*5108	3*5109	1*5110	2*5210	(7) =	200.00
.....	1*5107	1*5108	1*5109	2*5210	(5) =	200.50
.....	2*5129	1*5108	1*5210	(4) =	201.00
.....	1*5107	1*5129	1*5109	1*5208	(4) =	201.50
.....	1*5108	4*5109	1*5110	(6) =	201.50
.....	1*5107	1*5108	2*5109	(4) =	202.00
1*5106	1*5110	(2) =	202.50
.....	1*5129	1*5108	1*5109	1*5110	2*5210	(6) =	203.00
.....	1*5107	1*5109	5*5210	(7) =	203.50
.....	1*5107	2*5109	1*5110	1*5210	1*5208	(6) =	203.50
.....	1*5129	4*5109	(5) =	204.00
1*5106	1*5210	1*5208	(3) =	204.00
.....	1*5129	1*5108	2*5109	1*5110	(5) =	204.50
.....	1*5107	1*5129	1*5108	(3) =	205.00
.....	2*5129	1*5109	2*5210	(5) =	205.50
.....	1*5129	1*5108	2*5109	1*5210	1*5208	(6) =	206.00
.....	5*5109	1*5110	1*5210	(7) =	206.00
.....	1*5107	3*5109	1*5210	(5) =	206.50
.....	2*5129	2*5109	(4) =	207.00
.....	2*5129	1*5108	1*5110	(4) =	207.50
.....	1*5107	1*5129	3*5210	(5) =	208.00
.....	1*5107	1*5108	1*5109	2*5210	1*5208	(6) =	208.50
.....	1*5107	1*5110	6*5210	(8) =	208.50
.....	2*5129	1*5108	1*5210	1*5208	(5) =	209.00
.....	1*5129	3*5109	1*5110	1*5210	(6) =	209.00
.....	1*5107	1*5129	1*5109	1*5210	(4) =	209.50
.....	3*5129	(3) =	210.00
1*5106	1*5110	1*5208	(3) =	210.50
.....	2*5129	1*5110	3*5210	(6) =	210.50
.....	1*5108	4*5109	2*5210	(7) =	211.00
1*5106	1*5107	2*5109	1*5110	2*5210	(6) =	211.50
.....	2*5210	(3) =	212.00
.....	1*5108	5*5109	(6) =	212.50
.....	1*5107	1*5129	1*5108	1*5208	(4) =	213.00
.....	1*5107	3*5109	1*5110	(5) =	213.00
1*5106	1*5109	(2) =	213.50
.....	1*5129	1*5108	2*5109	2*5210	(6) =	214.00
.....	1*5107	1*5129	1*5110	2*5210	(5) =	214.50
.....	2*5129	2*5109	1*5208	(5) =	215.00
.....	1*5107	1*5108	5*5210	(7) =	215.00
.....	1*5129	1*5108	3*5109	(5) =	215.50
.....	1*5107	1*5129	1*5109	1*5110	(4) =	216.00
.....	1*5108	1*5109	3*5210	(6) =	216.50
.....	2*5129	1*5108	2*5210	(5) =	217.00
.....	1*5107	1*5129	1*5109	1*5210	1*5208	(5) =	217.50
.....	1*5108	4*5109	1*5110	1*5210	(7) =	217.50
.....	3*5129	1*5208	(4) =	218.00
.....	1*5107	1*5108	2*5109	1*5210	(5) =	218.00
1*5106	1*5110	1*5210	(3) =	218.50
.....	1*5129	1*5108	1*5109	1*5110	3*5210	(7) =	219.00

M track length table

.....	1*5107	2*5109	1*5110	2*5210	1*5208	(7) =	219.50
.....	1*5107	1*5109	6*5210	(8) =	219.50
.....	1*5129	4*5109	1*5210	(6) =	220.00
1*5106	2*5210	1*5208	(4) =	220.00
.....	1*5129	1*5108	2*5109	1*5110	1*5210	(6) =	220.50
.....	1*5107	1*5129	1*5108	1*5210	(4) =	221.00
1*5106	1*5109	1*5208	(3) =	221.50
.....	2*5129	1*5109	3*5210	(6) =	221.50
.....	1*5129	1*5108	2*5109	2*5210	1*5208	(7) =	222.00
.....	5*5109	1*5110	2*5210	(8) =	222.00
.....	1*5107	3*5109	2*5210	(6) =	222.50
.....	2*5129	2*5109	1*5210	(5) =	223.00
.....	2*5129	1*5108	1*5110	1*5210	(5) =	223.50
.....	1*5107	4*5109	(5) =	224.00
.....	1*5107	1*5108	2*5109	1*5110	(5) =	224.50
1*5106	1*5108	(2) =	225.00
.....	1*5107	1*5129	1*5109	2*5210	(5) =	225.50
.....	3*5129	1*5210	(4) =	226.00
1*5106	1*5110	1*5210	1*5208	(4) =	226.50
.....	1*5129	4*5109	1*5110	(6) =	226.50
.....	1*5107	1*5129	2*5109	(4) =	227.00
.....	1*5107	1*5129	1*5108	1*5110	(4) =	227.50
1*5106	3*5210	(4) =	228.00
.....	1*5108	5*5109	1*5210	(7) =	228.50
.....	1*5107	1*5129	1*5108	1*5210	1*5208	(5) =	229.00
.....	1*5107	3*5109	1*5110	1*5210	(6) =	229.00
1*5106	1*5109	1*5210	(3) =	229.50
.....	1*5107	2*5129	(3) =	230.00
.....	1*5107	1*5129	1*5110	3*5210	(6) =	230.50
.....	2*5129	2*5109	1*5210	1*5208	(6) =	231.00
.....	1*5107	1*5108	6*5210	(8) =	231.00
.....	1*5129	1*5108	3*5109	1*5210	(6) =	231.50
.....	1*5107	1*5129	1*5109	1*5110	1*5210	(5) =	232.00
.....	3*5129	1*5110	(4) =	232.50
.....	2*5129	1*5108	3*5210	(6) =	233.00
1*5106	1*5108	1*5208	(3) =	233.00
.....	1*5107	1*5129	1*5109	2*5210	1*5208	(6) =	233.50
.....	1*5108	4*5109	1*5110	2*5210	(8) =	233.50
.....	3*5129	1*5210	1*5208	(5) =	234.00
.....	1*5107	1*5108	2*5109	2*5210	(6) =	234.00
1*5106	1*5110	2*5210	(4) =	234.50
.....	1*5107	1*5129	2*5109	1*5208	(5) =	235.00
.....	1*5108	5*5109	1*5110	(7) =	235.00
.....	1*5107	1*5108	3*5109	(5) =	235.50
1*5106	1*5109	1*5110	(3) =	236.00
.....	1*5129	1*5108	2*5109	1*5110	2*5210	(7) =	236.50
.....	1*5107	1*5129	1*5108	2*5210	(5) =	237.00
.....	1*5129	5*5109	(6) =	237.50
1*5106	1*5109	1*5210	1*5208	(4) =	237.50
.....	1*5107	2*5129	1*5208	(4) =	238.00
.....	1*5129	1*5108	3*5109	1*5110	(6) =	238.00
.....	1*5107	1*5129	1*5108	1*5109	(4) =	238.50
.....	2*5129	2*5109	2*5210	(6) =	239.00
.....	2*5129	1*5108	1*5110	2*5210	(6) =	239.50
.....	1*5107	4*5109	1*5210	(6) =	240.00
.....	2*5129	3*5109	(5) =	240.50
1*5106	1*5108	1*5210	(3) =	241.00
.....	1*5107	1*5129	1*5109	3*5210	(6) =	241.50
.....	3*5129	2*5210	(5) =	242.00
1*5106	1*5110	2*5210	1*5208	(5) =	242.50
.....	1*5129	4*5109	1*5110	1*5210	(7) =	242.50
.....	1*5107	1*5129	2*5109	1*5210	(5) =	243.00
.....	3*5129	1*5109	(4) =	243.50
1*5106	4*5210	(5) =	244.00
1*5106	1*5109	1*5110	1*5208	(4) =	244.00
.....	1*5108	5*5109	2*5210	(8) =	244.50
.....	1*5107	1*5129	1*5108	2*5210	1*5208	(6) =	245.00
.....	1*5107	3*5109	1*5110	2*5210	(7) =	245.00
1*5106	1*5109	2*5210	(4) =	245.50
.....	1*5107	2*5129	1*5210	(4) =	246.00
.....	1*5107	1*5129	1*5108	1*5109	1*5208	(5) =	246.50
.....	1*5107	4*5109	1*5110	(6) =	246.50
1*5106	2*5109	(3) =	247.00
1*5106	1*5108	1*5110	(3) =	247.50
.....	1*5107	1*5129	1*5109	1*5110	2*5210	(6) =	248.00
.....	3*5129	1*5110	1*5210	(5) =	248.50
1*5106	1*5108	1*5210	1*5208	(4) =	249.00
.....	1*5129	1*5108	4*5109	(6) =	249.00
.....	1*5107	1*5129	2*5109	1*5110	(5) =	249.50
1*5106	1*5129	(2) =	250.00
1*5106	1*5110	3*5210	(5) =	250.50
.....	1*5107	1*5129	2*5109	1*5210	1*5208	(6) =	251.00
.....	1*5108	5*5109	1*5110	1*5210	(8) =	251.00

M track length table

.....	3*5129	1*5109	1*5208	(5) =	251.50
.....	1*5107	1*5108	3*5109	1*5210	(6) =	251.50
1*5106	1*5109	1*5110	1*5210	(4) =	252.00
.....	1*5107	2*5129	1*5110	(4) =	252.50
.....	1*5107	1*5129	1*5108	3*5210	(6) =	253.00
.....	1*5129	5*5109	1*5210	(7) =	253.50
1*5106	1*5109	2*5210	1*5208	(5) =	253.50
.....	1*5107	2*5129	1*5210	1*5208	(5) =	254.00
.....	1*5107	1*5129	1*5108	3*5109	1*5110	1*5210	(7) =	254.00
.....	1*5107	1*5129	1*5108	1*5109	1*5210	(5) =	254.50
.....	3*5129	1*5108	(4) =	255.00
.....	2*5129	1*5108	1*5110	3*5210	(7) =	255.50
1*5106	1*5108	1*5110	1*5208	(4) =	255.50
.....	1*5107	4*5109	2*5210	(7) =	256.00
.....	2*5129	3*5109	1*5210	(6) =	256.50
1*5106	1*5108	2*5210	(4) =	257.00
.....	1*5107	5*5109	(6) =	257.50
.....	1*5107	1*5108	3*5109	1*5110	(6) =	258.00
1*5106	1*5129	1*5208	(3) =	258.00
.....	3*5129	3*5210	(6) =	258.00
1*5106	1*5108	1*5109	(3) =	258.50
.....	1*5107	1*5129	2*5109	2*5210	(6) =	259.00
.....	3*5129	1*5109	1*5210	(5) =	259.50
1*5106	5*5210	(6) =	260.00
1*5106	1*5109	1*5110	1*5210	1*5208	(5) =	260.00
.....	1*5107	1*5129	3*5109	(5) =	260.50
.....	1*5107	1*5129	1*5108	1*5109	1*5110	(5) =	261.00
1*5106	1*5109	3*5210	(5) =	261.50
.....	1*5107	2*5129	2*5210	(5) =	262.00
.....	1*5107	1*5129	1*5108	1*5109	1*5210	1*5208	(6) =	262.50
.....	1*5107	4*5109	1*5110	1*5210	(7) =	262.50
1*5106	2*5109	1*5210	(4) =	263.00
.....	1*5107	2*5129	1*5109	(4) =	263.50
1*5106	1*5108	1*5110	1*5210	(4) =	263.50
.....	1*5107	1*5129	1*5109	1*5110	3*5210	(7) =	264.00
.....	3*5129	1*5110	2*5210	(6) =	264.50
1*5106	1*5108	2*5210	1*5208	(5) =	265.00
.....	1*5129	1*5108	4*5109	1*5210	(7) =	265.00
.....	1*5107	1*5129	2*5109	1*5110	1*5210	(6) =	265.50
1*5106	1*5129	1*5210	(3) =	266.00
1*5106	1*5108	1*5109	1*5208	(4) =	266.50
1*5106	1*5110	4*5210	(6) =	266.50
.....	1*5107	1*5129	2*5109	2*5210	1*5208	(7) =	267.00
.....	1*5108	5*5109	1*5110	2*5210	(9) =	267.00
.....	3*5129	1*5109	1*5210	1*5208	(6) =	267.50
.....	1*5107	1*5108	3*5109	2*5210	(7) =	267.50
1*5106	1*5109	1*5110	2*5210	(5) =	268.00
.....	1*5107	2*5129	1*5110	1*5210	(5) =	268.50
.....	1*5107	1*5108	4*5109	(6) =	269.00
1*5106	2*5109	1*5110	(4) =	269.50
1*5106	1*5107	(2) =	270.00
.....	1*5107	1*5129	1*5108	1*5109	2*5210	(6) =	270.50
.....	3*5129	1*5108	1*5210	(5) =	271.00
.....	1*5107	2*5129	1*5109	1*5208	(5) =	271.50
.....	1*5129	1*5108	4*5109	1*5110	(7) =	271.50
1*5106	1*5108	1*5110	1*5210	1*5208	(5) =	271.50
.....	1*5107	1*5129	1*5108	2*5109	(5) =	272.00
1*5106	1*5129	1*5110	(3) =	272.50
1*5106	1*5108	3*5210	(5) =	273.00
.....	1*5107	5*5109	1*5210	(7) =	273.50
.....	2*5129	4*5109	(6) =	274.00
1*5106	1*5129	1*5210	1*5208	(4) =	274.00
1*5106	1*5108	1*5109	1*5210	(4) =	274.50
.....	1*5107	2*5129	1*5108	(4) =	275.00
.....	3*5129	1*5109	2*5210	(6) =	275.50
1*5106	6*5210	(7) =	276.00
1*5106	1*5109	1*5110	2*5210	1*5208	(6) =	276.00
.....	1*5107	1*5129	3*5109	1*5210	(6) =	276.50
.....	3*5129	2*5109	(5) =	277.00
.....	3*5129	1*5108	1*5110	(5) =	277.50
.....	1*5107	2*5129	3*5210	(6) =	278.00
1*5106	1*5107	1*5208	(3) =	278.00
.....	1*5107	1*5129	1*5108	1*5109	2*5210	1*5208	(7) =	278.50
.....	1*5107	4*5109	1*5110	2*5210	(8) =	278.50
1*5106	2*5109	2*5210	(5) =	279.00
.....	1*5107	2*5129	1*5109	1*5210	(5) =	279.50
1*5106	1*5108	1*5110	2*5210	(5) =	279.50
.....	4*5129	(4) =	280.00
1*5106	3*5109	(4) =	280.50
1*5106	1*5108	1*5109	1*5110	(4) =	281.00
.....	1*5107	1*5129	2*5109	1*5110	2*5210	(7) =	281.50
1*5106	1*5129	2*5210	(4) =	282.00
1*5106	1*5108	1*5109	1*5210	1*5208	(5) =	282.50

M track length table

.....	1*5129	1*5108	5*5109	(7) =	282.50
1*5106	1*5110	5*5210	(7) =	282.50
.....	1*5107	2*5129	1*5108	(5) =	283.00
.....	1*5107	1*5129	3*5109	1*5110	(6) =	283.00
1*5106	1*5129	1*5109	(3) =	283.50
1*5106	1*5109	1*5110	3*5210	(6) =	284.00
.....	1*5107	2*5129	1*5110	2*5210	(6) =	284.50
.....	1*5107	1*5108	4*5109	1*5210	(7) =	285.00
.....	3*5129	2*5109	(6) =	285.00
1*5106	2*5109	1*5110	1*5210	(5) =	285.50
1*5106	1*5107	1*5210	(3) =	286.00
.....	1*5107	1*5129	1*5108	1*5109	3*5210	(7) =	286.50
.....	3*5129	1*5108	2*5210	(6) =	287.00
.....	1*5107	2*5129	1*5109	1*5210	(6) =	287.50
.....	1*5129	1*5108	4*5109	1*5110	1*5210	(8) =	287.50
1*5106	1*5108	1*5110	2*5210	(6) =	287.50
.....	4*5129	(5) =	288.00
.....	1*5107	1*5129	1*5108	2*5109	1*5210	(6) =	288.00
1*5106	1*5129	1*5110	1*5210	(4) =	288.50
1*5106	1*5108	4*5210	(6) =	289.00
1*5106	1*5108	1*5109	1*5110	(5) =	289.00
.....	1*5107	5*5109	2*5210	(8) =	289.50
.....	2*5129	4*5109	1*5210	(7) =	290.00
1*5106	1*5129	2*5210	(5) =	290.00
1*5106	1*5108	1*5109	2*5210	(5) =	290.50
.....	1*5107	2*5129	1*5108	1*5210	(5) =	291.00
.....	1*5107	1*5108	4*5109	1*5110	(7) =	291.50
1*5106	1*5129	1*5109	(4) =	291.50
.....	3*5129	1*5109	3*5210	(7) =	291.50
1*5106	1*5108	2*5109	(4) =	292.00
1*5106	1*5107	1*5110	(3) =	292.50
.....	3*5129	2*5109	1*5210	(6) =	293.00
.....	3*5129	1*5108	1*5110	1*5210	(6) =	293.50
1*5106	1*5107	1*5210	(4) =	294.00
.....	1*5107	1*5129	(6) =	294.00
.....	1*5107	1*5129	1*5108	2*5109	1*5110	(6) =	294.50
1*5106	1*5129	1*5108	(3) =	295.00
.....	1*5107	2*5129	1*5109	2*5210	(6) =	295.50
1*5106	1*5108	1*5110	3*5210	(6) =	295.50
.....	4*5129	1*5210	(5) =	296.00
1*5106	3*5109	1*5210	(5) =	296.50
.....	1*5107	2*5129	2*5109	(5) =	297.00
1*5106	1*5108	1*5109	1*5110	1*5210	(5) =	297.00
.....	1*5107	2*5129	1*5108	1*5110	(5) =	297.50
1*5106	1*5129	3*5210	(5) =	298.00
1*5106	1*5108	1*5109	2*5210	(6) =	298.50
.....	1*5129	1*5108	5*5109	1*5210	(8) =	298.50
1*5106	1*5110	6*5210	(8) =	298.50
.....	1*5107	2*5129	1*5108	1*5210	(6) =	299.00
.....	1*5107	1*5129	3*5109	1*5110	1*5210	(7) =	299.00
1*5106	1*5129	1*5109	1*5210	(4) =	299.50
.....	1*5107	3*5129	(4) =	300.00
.....	1*5107	2*5129	1*5110	3*5210	(7) =	300.50
1*5106	1*5107	1*5110	(4) =	300.50
.....	1*5107	1*5108	4*5109	2*5210	(8) =	301.00
.....	3*5129	2*5109	1*5210	(7) =	301.00
1*5106	2*5109	1*5110	2*5210	(6) =	301.50
1*5106	1*5107	2*5210	(4) =	302.00
.....	4*5129	1*5110	(5) =	302.50
1*5106	1*5129	1*5108	(4) =	303.00
1*5106	3*5109	1*5110	(5) =	303.00
1*5106	1*5107	1*5109	(3) =	303.50
.....	4*5129	1*5210	(6) =	304.00
.....	1*5107	1*5129	1*5108	2*5109	2*5210	(7) =	304.00
1*5106	1*5129	1*5110	2*5210	(5) =	304.50
1*5106	1*5108	1*5109	1*5110	1*5210	(6) =	305.00
.....	1*5107	2*5129	2*5109	(6) =	305.00
1*5106	1*5108	5*5210	(7) =	305.00
.....	1*5107	1*5129	1*5108	3*5109	(6) =	305.50
1*5106	1*5129	1*5109	1*5110	(4) =	306.00
1*5106	1*5108	1*5109	3*5210	(6) =	306.50
.....	1*5107	2*5129	1*5108	2*5210	(6) =	307.00
.....	2*5129	5*5109	(7) =	307.50
1*5106	1*5129	1*5109	1*5210	(5) =	307.50
1*5106	1*5108	2*5109	1*5210	(5) =	308.00
1*5106	1*5107	1*5110	1*5210	(4) =	308.50
.....	3*5129	2*5109	2*5210	(7) =	309.00
.....	3*5129	1*5108	1*5110	2*5210	(7) =	309.50
1*5106	1*5107	2*5210	(5) =	310.00
.....	1*5107	1*5129	4*5109	1*5210	(7) =	310.00
.....	3*5129	3*5109	(6) =	310.50
1*5106	1*5129	1*5108	1*5210	(4) =	311.00
.....	1*5107	2*5129	1*5109	3*5210	(7) =	311.50

M track length table

1*5106			1*5108		1*5110	4*5210		(7) =	311.50
1*5106	1*5107			1*5109			1*5208	(4) =	311.50
		4*5129				2*5210		(6) =	312.00
1*5106				3*5109		2*5210		(6) =	312.50
1*5106			1*5108	1*5109	1*5110	2*5210		(6) =	313.00
	1*5107	2*5129		2*5109		1*5210		(6) =	313.00
		4*5129		1*5109				(5) =	313.50
1*5106				4*5109				(5) =	314.00
1*5106			1*5108	2*5109	1*5110			(5) =	314.50
1*5106	1*5107		1*5108					(3) =	315.00
1*5106		1*5129		1*5109		2*5210		(5) =	315.50
	1*5107	3*5129				1*5210		(5) =	316.00
1*5106	1*5107				1*5110	1*5210	1*5208	(5) =	316.50
	1*5107	1*5129		4*5109	1*5110			(7) =	316.50
1*5106		1*5129		2*5109				(4) =	317.00
1*5106		1*5129	1*5108		1*5110			(4) =	317.50
1*5106	1*5107					3*5210		(5) =	318.00
		4*5129			1*5110	1*5210		(6) =	318.50
1*5106		1*5129	1*5108			1*5210	1*5208	(5) =	319.00
1*5106				3*5109	1*5110	1*5210		(6) =	319.00
1*5106	1*5107			1*5109		1*5210		(4) =	319.50
1*5106		2*5129						(3) =	320.00
1*5106		1*5129			1*5110	3*5210		(6) =	320.50
1*5106			1*5108	1*5109	1*5110	2*5210	1*5208	(7) =	321.00
1*5106			1*5108			6*5210		(8) =	321.00
	1*5107	2*5129		2*5109		1*5210	1*5208	(7) =	321.00
		4*5129		1*5109			1*5208	(6) =	321.50
	1*5107	1*5129	1*5108	3*5109		1*5210		(7) =	321.50
1*5106		1*5129		1*5109	1*5110	1*5210		(5) =	322.00
	1*5107	3*5129			1*5110			(5) =	322.50
	1*5107	2*5129	1*5108			3*5210		(7) =	323.00
1*5106	1*5107		1*5108				1*5208	(4) =	323.00
		2*5129		5*5109		1*5210		(8) =	323.50
1*5106		1*5129		1*5109		2*5210	1*5208	(6) =	323.50
1*5106			1*5108	2*5109		2*5210		(6) =	324.00
1*5106	1*5107				1*5110	2*5210		(5) =	324.50
		4*5129	1*5108					(5) =	325.00
1*5106			1*5108	3*5109				(5) =	325.50
1*5106	1*5107			1*5109	1*5110			(4) =	326.00
		3*5129		3*5109		1*5210		(7) =	326.50
1*5106		1*5129	1*5108			2*5210		(5) =	327.00
1*5106	1*5107			1*5109		1*5210	1*5208	(5) =	327.50
	1*5107	1*5129		5*5109				(7) =	327.50
	1*5107	1*5129	1*5108	3*5109	1*5110			(7) =	328.00
1*5106		2*5129					1*5208	(4) =	328.00
		4*5129				3*5210		(7) =	328.00
1*5106		1*5129	1*5108	1*5109				(4) =	328.50
	1*5107	2*5129		2*5109		2*5210		(7) =	329.00
1*5106			1*5108	1*5109	1*5110	3*5210		(7) =	329.00
		4*5129		1*5109		1*5210		(6) =	329.50
1*5106				4*5109		1*5210		(6) =	330.00
1*5106			1*5108	2*5109	1*5110	1*5210		(6) =	330.50
	1*5107	2*5129		3*5109				(6) =	330.50
1*5106	1*5107		1*5108			1*5210		(4) =	331.00
1*5106		1*5129		1*5109		3*5210		(6) =	331.50
	1*5107	3*5129				2*5210		(6) =	332.00
1*5106	1*5107				1*5110	2*5210	1*5208	(6) =	332.50
	1*5107	1*5129		4*5109	1*5110	1*5210		(8) =	332.50
1*5106		1*5129		2*5109		1*5210		(5) =	333.00
	1*5107	3*5129		1*5109				(5) =	333.50
1*5106		1*5129	1*5108		1*5110	1*5210		(5) =	333.50
1*5106	1*5107					4*5210		(6) =	334.00
1*5106	1*5107			1*5109	1*5110		1*5208	(5) =	334.00
		4*5129			1*5110	2*5210		(7) =	334.50
1*5106		1*5129	1*5108			2*5210	1*5208	(6) =	335.00
1*5106				3*5109	1*5110	2*5210		(7) =	335.00
1*5106	1*5107			1*5109		2*5210		(5) =	335.50
1*5106		2*5129				1*5210		(4) =	336.00
1*5106		1*5129	1*5108	1*5109			1*5208	(5) =	336.50
1*5106				4*5109	1*5110			(6) =	336.50
1*5106	1*5107			2*5109				(4) =	337.00
1*5106	1*5107		1*5108		1*5110			(4) =	337.50
1*5106		1*5129		1*5109	1*5110	2*5210		(6) =	338.00
	1*5107	3*5129			1*5110	1*5210		(6) =	338.50
	1*5107	1*5129	1*5108	4*5109				(7) =	339.00
1*5106	1*5107		1*5108			1*5210	1*5208	(5) =	339.00
1*5106		1*5129		2*5109	1*5110			(5) =	339.50
1*5106	1*5107	1*5129						(3) =	340.00
1*5106	1*5107				1*5110	3*5210		(6) =	340.50
		4*5129	1*5108			1*5210		(6) =	341.00
1*5106			1*5108	3*5109		1*5210		(6) =	341.50
1*5106	1*5107			1*5109	1*5110	1*5210		(5) =	342.00
1*5106		2*5129			1*5110			(4) =	342.50

M track length table

1*5106	1*5129	1*5108	3*5210	(6) =	343.00
1*5106	1*5107	1*5109	2*5210	1*5208	(6) =	343.50
.....	1*5107	1*5129	5*5109	1*5210	(8) =	343.50
.....	3*5129	4*5109	(7) =	344.00
1*5106	2*5129	1*5210	1*5208	(5) =	344.00
1*5106	1*5129	1*5108	1*5109	1*5210	(5) =	344.50
.....	1*5107	3*5129	1*5108	(5) =	345.00
1*5106	1*5107	1*5108	1*5110	1*5208	(5) =	345.50
.....	4*5129	1*5109	2*5210	(7) =	345.50
1*5106	4*5109	2*5210	(7) =	346.00
1*5106	1*5108	2*5109	1*5110	2*5210	(7) =	346.50
.....	1*5107	2*5129	3*5109	1*5210	(7) =	346.50
1*5106	1*5107	1*5108	2*5210	(5) =	347.00
.....	4*5129	1*5108	1*5110	(6) =	347.50
1*5106	5*5109	(6) =	347.50
1*5106	1*5107	1*5129	1*5208	(4) =	348.00
1*5106	1*5108	3*5109	1*5110	(6) =	348.00
1*5106	1*5107	1*5108	1*5109	(4) =	348.50
1*5106	1*5129	2*5109	2*5210	(6) =	349.00
.....	1*5107	3*5129	1*5109	1*5210	(6) =	349.50
1*5106	1*5129	1*5108	1*5110	2*5210	(6) =	349.50
.....	5*5129	(5) =	350.00
1*5106	1*5129	3*5109	(5) =	350.50
1*5106	1*5129	1*5108	1*5109	1*5110	(5) =	351.00
1*5106	1*5107	1*5109	3*5210	(6) =	351.50
1*5106	2*5129	2*5210	(5) =	352.00
1*5106	1*5129	1*5108	1*5109	1*5210	1*5208	(6) =	352.50
1*5106	4*5109	1*5110	1*5210	(7) =	352.50
1*5106	1*5107	2*5109	1*5210	(5) =	353.00
1*5106	2*5129	1*5109	(4) =	353.50
1*5106	1*5129	1*5109	1*5110	3*5210	(7) =	354.00
.....	1*5107	3*5129	1*5110	2*5210	(7) =	354.50
.....	1*5107	1*5129	1*5108	4*5109	1*5210	(8) =	355.00
1*5106	1*5107	1*5108	2*5210	1*5208	(6) =	355.00
1*5106	1*5129	2*5109	1*5110	1*5210	(6) =	355.50
1*5106	1*5107	1*5129	1*5210	(4) =	356.00
1*5106	1*5107	1*5110	4*5210	(7) =	356.50
1*5106	1*5107	1*5108	1*5109	1*5208	(5) =	356.50
.....	4*5129	1*5108	2*5210	(7) =	357.00
1*5106	1*5108	3*5109	2*5210	(7) =	357.50
1*5106	1*5107	1*5109	1*5110	2*5210	(6) =	358.00
1*5106	2*5129	1*5110	1*5210	(5) =	358.50
1*5106	1*5108	4*5109	(6) =	359.00
1*5106	1*5107	2*5109	1*5110	(5) =	359.50
2*5106	(2) =	360.00
1*5106	1*5129	1*5108	1*5109	2*5210	(6) =	360.50
.....	1*5107	3*5129	1*5108	1*5210	(6) =	361.00
.....	1*5107	1*5129	1*5108	4*5109	1*5110	(8) =	361.50
1*5106	2*5129	1*5109	1*5208	(5) =	361.50
.....	4*5129	1*5109	3*5210	(8) =	361.50
1*5106	1*5129	1*5108	2*5109	(5) =	362.00
1*5106	1*5107	1*5129	1*5110	(4) =	362.50
1*5106	1*5107	1*5108	3*5210	(6) =	363.00
.....	4*5129	1*5108	1*5110	1*5210	(7) =	363.50
1*5106	5*5109	1*5210	(7) =	363.50
1*5106	1*5107	1*5129	1*5210	1*5208	(5) =	364.00
1*5106	1*5108	3*5109	1*5110	1*5210	(7) =	364.00
.....	1*5107	2*5129	4*5109	(7) =	364.00
1*5106	1*5107	1*5108	1*5109	1*5210	(5) =	364.50
1*5106	2*5129	1*5108	(4) =	365.00
1*5106	1*5129	1*5108	1*5110	3*5210	(7) =	365.50
.....	1*5107	3*5129	1*5109	2*5210	(7) =	365.50
.....	5*5129	1*5210	(6) =	366.00
1*5106	1*5129	3*5109	1*5210	(6) =	366.50
1*5106	1*5129	1*5108	1*5109	1*5110	1*5210	(6) =	367.00
.....	1*5107	3*5129	2*5109	(6) =	367.00
.....	1*5107	3*5129	1*5108	1*5110	(6) =	367.50
2*5106	1*5208	(3) =	368.00
1*5106	2*5129	3*5210	(6) =	368.00
1*5106	1*5129	1*5108	1*5109	2*5210	1*5208	(7) =	368.50
1*5106	4*5109	1*5110	2*5210	(8) =	368.50
1*5106	1*5107	2*5109	2*5210	(6) =	369.00
1*5106	2*5129	1*5109	1*5210	(5) =	369.50
.....	1*5107	4*5129	(5) =	370.00
1*5106	1*5107	3*5109	(5) =	370.50
1*5106	1*5107	1*5108	1*5109	1*5110	(5) =	371.00
1*5106	1*5129	2*5109	1*5110	2*5210	(7) =	371.50
1*5106	1*5107	1*5129	2*5210	(5) =	372.00
.....	5*5129	1*5110	(6) =	372.50
1*5106	2*5129	1*5108	1*5208	(5) =	373.00
1*5106	1*5129	3*5109	1*5110	(6) =	373.00
1*5106	1*5107	1*5129	1*5109	(4) =	373.50
1*5106	1*5107	1*5109	1*5110	3*5210	(7) =	374.00

M track length table

1*5106	2*5129	1*5110	2*5210	(6) =	374.50
1*5106	1*5108	4*5109	1*5210	(7) =	375.00
1*5106	1*5107	2*5109	1*5110	1*5210	(6) =	375.50
2*5106	1*5210	(3) =	376.00
1*5106	1*5129	1*5108	1*5109	3*5210	(7) =	376.50
.....	1*5107	3*5129	1*5108	2*5210	(7) =	377.00
.....	3*5129	5*5109	(8) =	377.50
1*5106	2*5129	1*5109	1*5210	1*5208	(6) =	377.50
1*5106	3*5129	1*5108	4*5109	1*5210	(6) =	378.00
1*5106	1*5107	1*5129	1*5110	1*5210	(5) =	378.50
1*5106	1*5107	1*5108	4*5210	(7) =	379.00
1*5106	1*5107	1*5108	1*5109	1*5110	1*5208	(6) =	379.00
1*5106	5*5109	2*5210	(8) =	379.50
.....	4*5129	1*5108	1*5110	2*5210	(8) =	379.50
1*5106	1*5107	1*5129	2*5210	1*5208	(6) =	380.00
1*5106	1*5108	3*5109	1*5110	2*5210	(8) =	380.00
.....	1*5107	2*5129	4*5109	1*5210	(8) =	380.00
1*5106	1*5107	1*5108	1*5109	2*5210	(6) =	380.50
1*5106	2*5129	1*5108	1*5210	(5) =	381.00
1*5106	1*5107	1*5129	1*5109	1*5208	(5) =	381.50
1*5106	1*5108	4*5109	1*5110	(7) =	381.50
1*5106	1*5107	1*5108	2*5109	(5) =	382.00
2*5106	1*5110	(3) =	382.50
1*5106	1*5129	1*5108	1*5109	1*5110	2*5210	(7) =	383.00
.....	1*5107	3*5129	2*5109	1*5210	(7) =	383.00
.....	5*5129	1*5109	(6) =	383.50
1*5106	1*5129	4*5109	(6) =	384.00
2*5106	1*5210	1*5208	(4) =	384.00
1*5106	1*5129	1*5108	2*5109	1*5110	(6) =	384.50
1*5106	1*5107	1*5129	1*5108	(4) =	385.00
1*5106	2*5129	1*5109	2*5210	(6) =	385.50
.....	1*5107	4*5129	1*5210	(6) =	386.00
1*5106	1*5107	3*5109	1*5210	(6) =	386.50
1*5106	2*5129	2*5109	(5) =	387.00
1*5106	2*5129	1*5108	1*5110	(5) =	387.50
1*5106	1*5107	1*5129	3*5210	(6) =	388.00
.....	5*5129	1*5110	1*5210	(7) =	388.50
1*5106	2*5129	1*5108	1*5210	1*5208	(6) =	389.00
1*5106	1*5129	3*5109	1*5110	1*5210	(7) =	389.00
1*5106	1*5107	1*5129	1*5109	1*5210	(5) =	389.50
1*5106	3*5129	(4) =	390.00
1*5106	2*5129	1*5110	3*5210	(7) =	390.50
2*5106	1*5110	1*5208	(4) =	390.50
1*5106	1*5108	4*5109	2*5210	(8) =	391.00
1*5106	1*5107	2*5109	1*5110	2*5210	(7) =	391.50
2*5106	2*5210	(4) =	392.00
.....	1*5107	4*5129	1*5110	(6) =	392.50
1*5106	1*5107	3*5109	1*5110	(6) =	393.00
1*5106	1*5107	1*5129	1*5108	1*5208	(5) =	393.00
2*5106	1*5109	(3) =	393.50
1*5106	1*5129	1*5108	2*5109	2*5210	(7) =	394.00
1*5106	1*5107	1*5129	1*5110	2*5210	(6) =	394.50
.....	5*5129	1*5108	(6) =	395.00
1*5106	1*5129	1*5108	3*5109	(6) =	395.50
1*5106	1*5107	1*5129	1*5109	1*5110	(5) =	396.00
1*5106	1*5107	1*5108	1*5109	3*5210	(7) =	396.50
1*5106	2*5129	1*5108	2*5210	(6) =	397.00
1*5106	1*5107	1*5129	1*5109	1*5210	1*5208	(6) =	397.50
1*5106	1*5108	4*5109	1*5110	1*5210	(8) =	397.50
.....	1*5107	2*5129	5*5109	(8) =	397.50
1*5106	1*5107	1*5108	2*5109	1*5210	(6) =	398.00
1*5106	3*5129	1*5208	(5) =	398.00
2*5106	1*5110	1*5210	(4) =	398.50
1*5106	1*5129	1*5108	1*5109	1*5110	3*5210	(8) =	399.00
.....	1*5107	3*5129	2*5109	2*5210	(8) =	399.00
.....	5*5129	1*5109	1*5210	(7) =	399.50
1*5106	1*5129	4*5109	1*5210	(7) =	400.00
2*5106	2*5210	1*5208	(5) =	400.00
1*5106	1*5129	1*5108	2*5109	1*5110	1*5210	(7) =	400.50
.....	1*5107	3*5129	3*5109	(7) =	400.50
1*5106	1*5107	1*5129	1*5108	1*5210	(5) =	401.00
1*5106	2*5129	1*5109	3*5210	(7) =	401.50
2*5106	1*5109	1*5208	(4) =	401.50
.....	1*5107	4*5129	2*5210	(7) =	402.00
1*5106	1*5107	3*5109	2*5210	(7) =	402.50
1*5106	2*5129	2*5109	1*5210	(6) =	403.00
.....	1*5107	4*5129	1*5109	(6) =	403.50
1*5106	2*5129	1*5108	1*5110	1*5210	(6) =	403.50
1*5106	1*5107	4*5109	(6) =	404.00
1*5106	1*5107	1*5108	2*5109	1*5110	(6) =	404.50
2*5106	1*5108	(3) =	405.00
1*5106	1*5107	1*5129	1*5109	2*5210	(6) =	405.50
1*5106	3*5129	1*5210	(5) =	406.00

M track length table

1*5106	1*5129	4*5109	1*5110	(7) =	406.50
2*5106	1*5110	1*5210	1*5208	(5) =	406.50
1*5106	1*5107	1*5129	2*5109	(5) =	407.00
1*5106	1*5107	1*5129	1*5108	1*5110	(5) =	407.50
2*5106	3*5210	(5) =	408.00
.....	1*5107	4*5129	1*5110	1*5210	(7) =	408.50
1*5106	1*5107	3*5109	1*5110	1*5210	(7) =	409.00
1*5106	1*5107	1*5129	1*5108	1*5210	1*5208	(6) =	409.00
2*5106	1*5109	1*5210	(4) =	409.50
1*5106	1*5107	2*5129	(4) =	410.00
1*5106	1*5107	1*5129	1*5110	3*5210	(7) =	410.50
.....	5*5129	1*5108	1*5210	(7) =	411.00
1*5106	1*5129	1*5108	3*5109	1*5210	(7) =	411.50
1*5106	1*5107	1*5129	1*5109	1*5110	1*5210	(6) =	412.00
1*5106	3*5129	1*5110	(5) =	412.50
2*5106	1*5108	1*5208	(4) =	413.00
1*5106	2*5129	1*5108	3*5210	(7) =	413.00
1*5106	1*5107	1*5129	1*5109	2*5210	1*5208	(7) =	413.50
1*5106	1*5108	4*5109	1*5110	2*5210	(9) =	413.50
.....	1*5107	2*5129	5*5109	1*5210	(9) =	413.50
1*5106	1*5107	1*5108	2*5109	2*5210	(7) =	414.00
1*5106	3*5129	1*5210	1*5208	(6) =	414.00
2*5106	1*5110	2*5210	(5) =	414.50
.....	1*5107	4*5129	1*5108	(6) =	415.00
1*5106	1*5107	1*5108	3*5109	(6) =	415.50
2*5106	1*5109	1*5110	(4) =	416.00
1*5106	1*5129	1*5108	2*5109	1*5110	2*5210	(8) =	416.50
.....	1*5107	3*5129	3*5109	1*5210	(8) =	416.50
1*5106	1*5107	1*5129	1*5108	2*5210	(6) =	417.00
.....	5*5129	1*5108	1*5110	(7) =	417.50
2*5106	1*5109	1*5210	1*5208	(5) =	417.50
1*5106	1*5129	5*5109	(7) =	417.50
1*5106	1*5107	2*5129	1*5208	(5) =	418.00
1*5106	1*5129	1*5108	3*5109	1*5110	(7) =	418.00
1*5106	1*5107	1*5129	1*5108	1*5109	(5) =	418.50
1*5106	2*5129	2*5109	2*5210	(7) =	419.00
.....	1*5107	4*5129	1*5109	1*5210	(7) =	419.50
1*5106	2*5129	1*5108	1*5110	2*5210	(7) =	419.50
.....	6*5129	(6) =	420.00
1*5106	2*5129	3*5109	(6) =	420.50
2*5106	1*5108	1*5210	(4) =	421.00
1*5106	1*5107	1*5129	1*5109	3*5210	(7) =	421.50
1*5106	3*5129	2*5210	(6) =	422.00
1*5106	1*5129	4*5109	1*5110	1*5210	(8) =	422.50
2*5106	1*5110	2*5210	1*5208	(6) =	422.50
1*5106	1*5107	1*5129	2*5109	1*5210	(6) =	423.00
1*5106	3*5129	1*5109	(5) =	423.50
2*5106	1*5109	1*5110	1*5208	(5) =	424.00
2*5106	4*5210	(6) =	424.00
.....	1*5107	4*5129	1*5110	2*5210	(8) =	424.50
1*5106	1*5107	3*5109	1*5110	2*5210	(8) =	425.00
1*5106	1*5107	1*5129	1*5108	2*5210	1*5208	(7) =	425.00
2*5106	1*5109	2*5210	(5) =	425.50
1*5106	1*5107	2*5129	1*5210	(5) =	426.00
1*5106	1*5107	4*5109	1*5110	(7) =	426.50
1*5106	1*5107	1*5129	1*5108	1*5109	1*5208	(6) =	426.50
2*5106	2*5109	(4) =	427.00
2*5106	1*5108	1*5110	(4) =	427.50
1*5106	1*5107	1*5129	1*5109	1*5110	2*5210	(7) =	428.00
1*5106	3*5129	1*5110	1*5210	(6) =	428.50
2*5106	1*5108	1*5210	1*5208	(5) =	429.00
1*5106	1*5129	1*5108	4*5109	(7) =	429.00
1*5106	1*5107	1*5129	2*5109	1*5110	(6) =	429.50
2*5106	1*5129	(3) =	430.00
2*5106	1*5110	3*5210	(6) =	430.50
.....	1*5107	4*5129	1*5108	1*5210	(7) =	431.00
1*5106	1*5107	1*5108	3*5109	1*5210	(7) =	431.50
1*5106	3*5129	1*5109	1*5208	(6) =	431.50
2*5106	1*5109	1*5110	1*5210	(5) =	432.00
1*5106	1*5107	2*5129	1*5110	(5) =	432.50
1*5106	1*5107	1*5129	1*5108	3*5210	(7) =	433.00
.....	5*5129	1*5108	1*5110	1*5210	(8) =	433.50
2*5106	1*5109	2*5210	1*5208	(6) =	433.50
1*5106	1*5129	5*5109	1*5210	(8) =	433.50
1*5106	1*5107	2*5129	1*5210	1*5208	(6) =	434.00
1*5106	1*5129	1*5108	3*5109	1*5110	1*5210	(8) =	434.00
.....	1*5107	3*5129	4*5109	(8) =	434.00
1*5106	1*5107	1*5129	1*5108	1*5109	1*5210	(6) =	434.50
1*5106	3*5129	1*5108	(5) =	435.00
1*5106	2*5129	1*5108	1*5110	3*5210	(8) =	435.50
.....	1*5107	4*5129	1*5109	2*5210	(8) =	435.50
2*5106	1*5108	1*5110	1*5208	(5) =	435.50
.....	6*5129	1*5210	(7) =	436.00

M track length table

1*5106	2*5129	3*5109	1*5210	(7) =	436.50
2*5106	1*5108	2*5210	(5) =	437.00
1*5106	1*5107	5*5109	(7) =	437.50
.....	1*5107	4*5129	1*5108	1*5110	(7) =	437.50
2*5106	1*5129	1*5208	(4) =	438.00
1*5106	3*5129	3*5210	(7) =	438.00
1*5106	1*5107	1*5108	3*5109	1*5110	(7) =	438.00
2*5106	1*5108	1*5109	(4) =	438.50
1*5106	1*5107	1*5129	2*5109	2*5210	(7) =	439.00
1*5106	3*5129	1*5109	1*5210	(6) =	439.50
.....	1*5107	5*5129	(6) =	440.00
1*5106	1*5107	1*5129	3*5109	(6) =	440.50
1*5106	1*5107	1*5129	1*5108	1*5109	1*5110	(6) =	441.00
2*5106	1*5109	3*5210	(6) =	441.50
1*5106	1*5107	2*5129	2*5210	(6) =	442.00
.....	6*5129	1*5110	(7) =	442.50
2*5106	2*5109	1*5210	(5) =	443.00
1*5106	1*5107	2*5129	1*5109	(5) =	443.50
2*5106	1*5108	1*5110	1*5210	(5) =	443.50
1*5106	1*5107	1*5129	1*5109	1*5110	3*5210	(8) =	444.00
1*5106	3*5129	1*5110	2*5210	(7) =	444.50
2*5106	1*5108	2*5210	1*5208	(6) =	445.00
1*5106	1*5129	1*5108	4*5109	1*5210	(8) =	445.00
1*5106	1*5107	1*5129	2*5109	1*5110	1*5210	(7) =	445.50
2*5106	1*5129	1*5210	(4) =	446.00
2*5106	1*5110	4*5210	(7) =	446.50
2*5106	1*5108	1*5109	1*5208	(5) =	446.50
.....	1*5107	4*5129	1*5108	2*5210	(8) =	447.00
1*5106	1*5107	1*5108	3*5109	2*5210	(8) =	447.50
1*5106	3*5129	1*5109	1*5210	1*5208	(7) =	447.50
2*5106	1*5109	1*5110	2*5210	(6) =	448.00
1*5106	1*5107	2*5129	1*5110	1*5210	(6) =	448.50
1*5106	1*5107	1*5108	4*5109	(7) =	449.00
2*5106	2*5109	1*5110	(5) =	449.50
2*5106	1*5107	(3) =	450.00
1*5106	1*5107	1*5129	1*5108	1*5109	2*5210	(7) =	450.50
1*5106	3*5129	1*5108	1*5210	(6) =	451.00
1*5106	1*5107	2*5129	1*5109	1*5208	(6) =	451.50
1*5106	1*5129	1*5108	4*5109	1*5110	(8) =	451.50
2*5106	1*5108	1*5110	1*5210	1*5208	(6) =	451.50
1*5106	1*5107	1*5129	1*5108	2*5109	(6) =	452.00
2*5106	1*5129	1*5110	(4) =	452.50
2*5106	1*5108	3*5210	(6) =	453.00
.....	6*5129	1*5109	(7) =	453.50
1*5106	2*5129	4*5109	(7) =	454.00
2*5106	1*5129	1*5210	1*5208	(5) =	454.00
2*5106	1*5108	1*5109	1*5210	(5) =	454.50
1*5106	1*5107	2*5129	1*5108	(5) =	455.00
1*5106	3*5129	1*5109	2*5210	(7) =	455.50
.....	1*5107	5*5129	1*5210	(7) =	456.00
1*5106	1*5107	1*5129	3*5109	1*5210	(7) =	456.50
1*5106	3*5129	2*5109	(6) =	457.00
1*5106	3*5129	1*5108	1*5110	(6) =	457.50
1*5106	1*5107	2*5129	3*5210	(7) =	458.00
2*5106	1*5107	1*5208	(4) =	458.00
.....	6*5129	1*5110	1*5210	(8) =	458.50
2*5106	2*5109	2*5210	(6) =	459.00
2*5106	1*5108	1*5110	2*5210	(6) =	459.50
1*5106	1*5107	2*5129	1*5109	1*5210	(6) =	459.50
1*5106	4*5129	(5) =	460.00
2*5106	3*5109	(5) =	460.50
2*5106	1*5108	1*5109	1*5110	(5) =	461.00
1*5106	1*5107	1*5129	2*5109	1*5110	2*5210	(8) =	461.50
2*5106	1*5129	2*5210	(5) =	462.00
.....	1*5107	5*5129	1*5110	(7) =	462.50
2*5106	1*5108	1*5109	1*5210	1*5208	(6) =	462.50
1*5106	1*5107	1*5129	3*5109	1*5110	(7) =	463.00
1*5106	1*5107	2*5129	1*5108	1*5208	(6) =	463.00
2*5106	1*5129	1*5109	(4) =	463.50
2*5106	1*5109	1*5110	3*5210	(7) =	464.00
1*5106	1*5107	2*5129	1*5110	2*5210	(7) =	464.50
.....	6*5129	1*5108	(7) =	465.00
2*5106	2*5109	1*5110	1*5210	(6) =	465.50
2*5106	1*5107	1*5210	(4) =	466.00
1*5106	1*5107	1*5129	1*5108	1*5109	3*5210	(8) =	466.50
1*5106	3*5129	1*5108	2*5210	(7) =	467.00
1*5106	1*5107	2*5129	1*5109	1*5210	1*5208	(7) =	467.50
1*5106	1*5129	1*5108	4*5109	1*5110	1*5210	(9) =	467.50
.....	1*5107	3*5129	5*5109	(9) =	467.50
2*5106	1*5108	1*5110	2*5210	1*5208	(7) =	467.50
1*5106	1*5107	1*5129	1*5108	2*5109	1*5210	(7) =	468.00
1*5106	4*5129	1*5208	(6) =	468.00
2*5106	1*5129	1*5110	1*5210	(5) =	468.50

M track length table

2*5106	1*5108	4*5210	(7) =	469.00
2*5106	1*5108	1*5109	1*5110	1*5208	(6) =	469.00
.....	6*5129	1*5109	1*5210	(8) =	469.50
1*5106	2*5129	4*5109	1*5210	(8) =	470.00
2*5106	1*5129	2*5210	1*5208	(6) =	470.00
2*5106	1*5108	1*5109	2*5210	(6) =	470.50
1*5106	1*5107	2*5129	1*5108	1*5210	(6) =	471.00
1*5106	1*5107	1*5108	4*5109	1*5110	(8) =	471.50
1*5106	3*5129	1*5109	3*5210	(8) =	471.50
2*5106	1*5129	1*5109	1*5208	(5) =	471.50
2*5106	1*5108	2*5109	(5) =	472.00
2*5106	1*5107	1*5110	(4) =	472.50
1*5106	3*5129	2*5109	1*5210	(7) =	473.00
.....	1*5107	5*5129	1*5109	(7) =	473.50
1*5106	3*5129	1*5108	1*5110	1*5210	(7) =	473.50
1*5106	1*5107	1*5129	4*5109	(7) =	474.00
2*5106	1*5107	1*5210	1*5208	(5) =	474.00
1*5106	1*5107	1*5129	1*5108	2*5109	1*5110	(7) =	474.50
2*5106	1*5129	1*5108	(4) =	475.00
2*5106	1*5108	1*5110	3*5210	(7) =	475.50
1*5106	1*5107	2*5129	1*5109	2*5210	(7) =	475.50
1*5106	4*5129	1*5210	(6) =	476.00
2*5106	3*5109	1*5210	(6) =	476.50
1*5106	1*5107	2*5129	2*5109	(6) =	477.00
2*5106	1*5108	1*5109	1*5110	1*5210	(6) =	477.00
1*5106	1*5107	2*5129	1*5108	1*5110	(6) =	477.50
2*5106	1*5129	3*5210	(6) =	478.00
.....	1*5107	5*5129	1*5110	1*5210	(8) =	478.50
2*5106	1*5108	1*5109	2*5210	1*5208	(7) =	478.50
1*5106	1*5107	1*5129	3*5109	1*5110	1*5210	(8) =	479.00
1*5106	1*5107	2*5129	1*5108	1*5210	1*5208	(7) =	479.00
2*5106	1*5129	1*5109	1*5210	(5) =	479.50
1*5106	1*5107	3*5129	(5) =	480.00
1*5106	1*5107	2*5129	1*5110	3*5210	(8) =	480.50
2*5106	1*5107	1*5110	1*5208	(5) =	480.50
.....	6*5129	1*5108	1*5210	(8) =	481.00
2*5106	2*5109	1*5110	2*5210	(7) =	481.50
2*5106	1*5107	2*5210	(5) =	482.00
1*5106	4*5129	1*5110	(6) =	482.50
2*5106	1*5129	1*5108	1*5208	(5) =	483.00
2*5106	3*5109	1*5110	(6) =	483.00
2*5106	1*5107	1*5109	(4) =	483.50
1*5106	1*5107	1*5129	1*5108	2*5109	2*5210	(8) =	484.00
1*5106	4*5129	1*5210	1*5208	(7) =	484.00
2*5106	1*5129	1*5110	2*5210	(6) =	484.50
.....	1*5107	5*5129	1*5108	(7) =	485.00
1*5106	1*5107	1*5129	1*5108	3*5109	(7) =	485.50
2*5106	1*5129	1*5109	1*5110	(5) =	486.00
2*5106	1*5108	1*5109	3*5210	(7) =	486.50
1*5106	1*5107	2*5129	1*5108	2*5210	(7) =	487.00
.....	6*5129	1*5108	1*5110	(8) =	487.50
2*5106	1*5129	1*5109	1*5210	1*5208	(6) =	487.50
1*5106	2*5129	5*5109	(8) =	487.50
2*5106	1*5108	2*5109	1*5210	(6) =	488.00
2*5106	1*5107	1*5110	1*5210	(5) =	488.50
1*5106	3*5129	2*5109	2*5210	(8) =	489.00
.....	1*5107	5*5129	1*5109	1*5210	(8) =	489.50
1*5106	3*5129	1*5108	1*5110	2*5210	(8) =	489.50
.....	7*5129	(7) =	490.00
2*5106	1*5107	2*5210	1*5208	(6) =	490.00
1*5106	3*5129	3*5109	(7) =	490.50
2*5106	1*5129	1*5108	1*5210	(5) =	491.00
1*5106	1*5107	2*5129	1*5109	3*5210	(8) =	491.50
2*5106	1*5108	1*5110	4*5210	(8) =	491.50
2*5106	1*5107	1*5109	1*5208	(5) =	491.50
1*5106	4*5129	2*5210	(7) =	492.00
2*5106	3*5109	2*5210	(7) =	492.50
1*5106	1*5107	2*5129	2*5109	1*5210	(7) =	493.00
2*5106	1*5108	1*5109	1*5110	2*5210	(7) =	493.00
1*5106	4*5129	1*5109	(6) =	493.50
2*5106	4*5109	(6) =	494.00
2*5106	1*5108	2*5109	1*5110	(6) =	494.50
2*5106	1*5107	1*5108	(4) =	495.00
2*5106	1*5129	1*5109	2*5210	(6) =	495.50
1*5106	1*5107	3*5129	1*5210	(6) =	496.00
2*5106	1*5107	1*5110	1*5210	1*5208	(6) =	496.50
1*5106	1*5107	1*5129	4*5109	1*5110	(8) =	496.50
2*5106	1*5129	2*5109	(5) =	497.00
2*5106	1*5129	1*5108	1*5110	(5) =	497.50
2*5106	1*5107	3*5210	(6) =	498.00
1*5106	4*5129	1*5110	1*5210	(7) =	498.50
2*5106	1*5129	1*5108	1*5210	1*5208	(6) =	499.00
2*5106	3*5109	1*5110	1*5210	(7) =	499.00

M track length table

2*5106	1*5107	1*5109	1*5210	(5) =	499.50
2*5106	2*5129	(4) =	500.00
2*5106	1*5129	1*5110	3*5210	(7) =	500.50
.....	1*5107	5*5129	1*5108	1*5210	(8) =	501.00
1*5106	1*5107	1*5129	1*5108	3*5109	1*5210	(8) =	501.50
1*5106	4*5129	1*5109	1*5208	(7) =	501.50
2*5106	1*5129	1*5109	1*5110	1*5210	(6) =	502.00
1*5106	1*5107	3*5129	1*5110	(6) =	502.50
2*5106	1*5107	1*5108	1*5208	(5) =	503.00
1*5106	1*5107	2*5129	1*5108	3*5210	(8) =	503.00
.....	6*5129	1*5108	1*5110	1*5210	(9) =	503.50
2*5106	1*5129	1*5109	2*5210	1*5208	(7) =	503.50
1*5106	2*5129	5*5109	1*5210	(9) =	503.50
2*5106	1*5108	2*5109	2*5210	(7) =	504.00
2*5106	1*5107	1*5110	2*5210	(6) =	504.50
1*5106	4*5129	1*5108	(6) =	505.00
2*5106	1*5108	3*5109	(6) =	505.50
2*5106	1*5107	1*5109	1*5110	(5) =	506.00
1*5106	3*5129	3*5109	1*5210	(8) =	506.50
2*5106	1*5129	1*5108	2*5210	(6) =	507.00
1*5106	1*5107	1*5129	5*5109	(8) =	507.50
.....	1*5107	5*5129	1*5108	1*5110	(8) =	507.50
2*5106	1*5107	1*5109	1*5210	1*5208	(6) =	507.50
2*5106	2*5129	1*5208	(5) =	508.00
1*5106	4*5129	3*5210	(8) =	508.00
1*5106	1*5107	1*5129	1*5108	3*5109	1*5110	(8) =	508.00
2*5106	1*5129	1*5108	1*5109	(5) =	508.50
1*5106	1*5107	2*5129	2*5109	2*5210	(8) =	509.00
2*5106	1*5108	1*5109	1*5110	3*5210	(8) =	509.00
1*5106	4*5129	1*5109	1*5210	(7) =	509.50
.....	1*5107	6*5129	(7) =	510.00
2*5106	4*5109	1*5210	(7) =	510.00
2*5106	1*5108	2*5109	1*5110	1*5210	(7) =	510.50
1*5106	1*5107	2*5129	3*5109	(7) =	510.50
2*5106	1*5107	1*5108	1*5210	(5) =	511.00
2*5106	1*5129	1*5109	3*5210	(7) =	511.50
1*5106	1*5107	3*5129	2*5210	(7) =	512.00
.....	7*5129	1*5110	(8) =	512.50
2*5106	1*5107	1*5110	2*5210	1*5208	(7) =	512.50
2*5106	1*5129	2*5109	1*5210	(6) =	513.00
1*5106	1*5107	3*5129	1*5109	(6) =	513.50
2*5106	1*5129	1*5108	1*5110	1*5210	(6) =	513.50
2*5106	1*5107	4*5210	(7) =	514.00
2*5106	1*5107	1*5109	1*5208	(6) =	514.00
1*5106	4*5129	1*5110	2*5210	(8) =	514.50
2*5106	1*5129	1*5108	2*5210	1*5208	(7) =	515.00
2*5106	3*5109	1*5110	2*5210	(8) =	515.00
2*5106	1*5107	1*5109	2*5210	(6) =	515.50
2*5106	2*5129	1*5210	(5) =	516.00
2*5106	1*5129	1*5108	1*5109	1*5208	(6) =	516.50
2*5106	4*5109	1*5110	(7) =	516.50
2*5106	1*5107	2*5109	(5) =	517.00
2*5106	1*5107	1*5108	1*5110	(5) =	517.50
2*5106	1*5129	1*5109	1*5110	2*5210	(7) =	518.00
1*5106	1*5107	3*5129	1*5110	1*5210	(7) =	518.50
1*5106	1*5107	1*5129	1*5108	4*5109	(8) =	519.00
2*5106	1*5107	1*5108	1*5210	1*5208	(6) =	519.00
2*5106	1*5129	2*5109	1*5110	(6) =	519.50
2*5106	1*5107	1*5129	(4) =	520.00
2*5106	1*5107	1*5110	3*5210	(7) =	520.50
1*5106	4*5129	1*5108	1*5210	(7) =	521.00
2*5106	1*5108	3*5109	1*5210	(7) =	521.50
2*5106	1*5107	1*5109	1*5110	1*5210	(6) =	522.00
2*5106	2*5129	1*5110	(5) =	522.50
2*5106	1*5129	1*5108	3*5210	(7) =	523.00
2*5106	1*5107	1*5109	2*5210	1*5208	(7) =	523.50
.....	7*5129	1*5109	(8) =	523.50
1*5106	3*5129	4*5109	(8) =	524.00
2*5106	2*5129	1*5210	1*5208	(6) =	524.00
2*5106	1*5129	1*5108	1*5109	1*5210	(6) =	524.50
1*5106	1*5107	3*5129	1*5108	(6) =	525.00
2*5106	1*5107	1*5108	1*5110	1*5208	(6) =	525.50
1*5106	4*5129	1*5109	2*5210	(8) =	525.50
.....	1*5107	6*5129	1*5210	(8) =	526.00
2*5106	4*5109	2*5210	(8) =	526.00
2*5106	1*5108	2*5109	1*5110	2*5210	(8) =	526.50
1*5106	1*5107	2*5129	3*5109	1*5210	(8) =	526.50
2*5106	1*5107	1*5108	2*5210	(6) =	527.00
1*5106	4*5129	1*5108	1*5110	(7) =	527.50
2*5106	5*5109	(7) =	527.50
2*5106	1*5108	3*5109	1*5110	(7) =	528.00
2*5106	1*5107	1*5129	1*5208	(5) =	528.00
2*5106	1*5107	1*5108	1*5109	(5) =	528.50

M track length table

2*5106	1*5129	2*5109	2*5210	(7) =	529.00
2*5106	1*5129	1*5108	1*5110	2*5210	(7) =	529.50
1*5106	1*5107	3*5129	1*5109	1*5210	(7) =	529.50
1*5106	5*5129	(6) =	530.00
2*5106	1*5129	3*5109	(6) =	530.50
2*5106	1*5129	1*5108	1*5109	1*5110	(6) =	531.00
2*5106	1*5107	1*5109	3*5210	(7) =	531.50
2*5106	2*5129	2*5210	(6) =	532.00
.....	1*5107	6*5129	1*5110	(8) =	532.50
2*5106	1*5129	1*5108	1*5109	1*5210	1*5208	(7) =	532.50
2*5106	4*5109	1*5110	1*5210	(8) =	532.50
2*5106	1*5107	2*5109	1*5210	(6) =	533.00
2*5106	2*5129	1*5109	(5) =	533.50
2*5106	1*5129	1*5109	1*5110	3*5210	(8) =	534.00
1*5106	1*5107	3*5129	1*5110	2*5210	(8) =	534.50
.....	7*5129	1*5108	(8) =	535.00
2*5106	1*5107	1*5108	2*5210	1*5208	(7) =	535.00
2*5106	1*5129	2*5109	1*5110	1*5210	(7) =	535.50
2*5106	1*5107	1*5129	1*5210	(5) =	536.00
2*5106	1*5107	1*5110	4*5210	(8) =	536.50
2*5106	1*5107	1*5108	1*5109	1*5208	(6) =	536.50
1*5106	4*5129	1*5108	2*5210	(8) =	537.00
2*5106	1*5108	3*5109	2*5210	(8) =	537.50
2*5106	1*5107	1*5109	1*5110	2*5210	(7) =	538.00
2*5106	2*5129	1*5110	1*5210	(6) =	538.50
2*5106	1*5108	4*5109	(7) =	539.00
2*5106	1*5107	2*5109	1*5110	(6) =	539.50
3*5106	(3) =	540.00
2*5106	1*5129	1*5108	1*5109	2*5210	(7) =	540.50
1*5106	1*5107	3*5129	1*5108	1*5210	(7) =	541.00
1*5106	1*5107	1*5129	1*5108	4*5109	1*5110	(9) =	541.50
1*5106	4*5129	1*5109	3*5210	(9) =	541.50
2*5106	2*5129	1*5109	1*5208	(6) =	541.50
2*5106	1*5129	1*5108	2*5109	(6) =	542.00
2*5106	1*5107	1*5129	1*5110	(5) =	542.50
2*5106	1*5107	1*5108	3*5210	(7) =	543.00
.....	1*5107	6*5129	1*5109	(8) =	543.50
1*5106	4*5129	1*5108	1*5110	1*5210	(8) =	543.50
2*5106	5*5109	1*5210	(8) =	543.50
1*5106	1*5107	2*5129	4*5109	(8) =	544.00
2*5106	1*5108	3*5109	1*5110	1*5210	(8) =	544.00
2*5106	1*5107	1*5129	1*5210	1*5208	(6) =	544.00
2*5106	1*5107	1*5108	1*5109	1*5210	(6) =	544.50
2*5106	2*5129	1*5108	(5) =	545.00
1*5106	1*5107	3*5129	1*5109	2*5210	(8) =	545.50
2*5106	1*5129	1*5108	1*5110	3*5210	(8) =	545.50
1*5106	5*5129	1*5210	(7) =	546.00
2*5106	1*5129	3*5109	1*5210	(7) =	546.50
1*5106	1*5107	3*5129	2*5109	(7) =	547.00
2*5106	1*5129	1*5108	1*5109	1*5110	1*5210	(7) =	547.00
1*5106	1*5107	3*5129	1*5108	1*5110	(7) =	547.50
3*5106	1*5208	(4) =	548.00
2*5106	2*5129	3*5210	(7) =	548.00
.....	1*5107	6*5129	1*5110	1*5210	(9) =	548.50
2*5106	1*5129	1*5108	1*5109	2*5210	1*5208	(8) =	548.50
2*5106	4*5109	1*5110	2*5210	(9) =	548.50
2*5106	1*5107	2*5109	2*5210	(7) =	549.00
2*5106	2*5129	1*5109	1*5210	(6) =	549.50
1*5106	1*5107	4*5129	(6) =	550.00
2*5106	1*5107	3*5109	(6) =	550.50
2*5106	1*5107	1*5108	1*5109	1*5110	(6) =	551.00
2*5106	1*5129	2*5109	1*5110	2*5210	(8) =	551.50
2*5106	1*5107	1*5129	2*5210	(6) =	552.00
1*5106	5*5129	1*5110	(7) =	552.50
2*5106	2*5129	1*5108	1*5208	(6) =	553.00
2*5106	1*5129	3*5109	1*5110	(7) =	553.00
2*5106	1*5107	1*5129	1*5109	(5) =	553.50
2*5106	1*5107	1*5109	1*5110	3*5210	(8) =	554.00
2*5106	2*5129	1*5110	2*5210	(7) =	554.50
.....	1*5107	6*5129	1*5108	(8) =	555.00
2*5106	1*5108	4*5109	1*5210	(8) =	555.00
2*5106	1*5107	2*5109	1*5110	1*5210	(7) =	555.50
3*5106	1*5210	(4) =	556.00
2*5106	1*5129	1*5108	1*5109	3*5210	(8) =	556.50
1*5106	1*5107	3*5129	1*5108	2*5210	(8) =	557.00
.....	7*5129	1*5108	1*5110	(9) =	557.50
2*5106	2*5129	1*5109	1*5210	1*5208	(7) =	557.50
1*5106	3*5129	5*5109	(9) =	557.50
2*5106	1*5129	1*5108	2*5109	1*5210	(7) =	558.00
2*5106	1*5107	1*5129	1*5110	1*5210	(6) =	558.50
2*5106	1*5107	1*5108	4*5210	(8) =	559.00
2*5106	1*5107	1*5108	1*5109	1*5110	1*5208	(7) =	559.00
2*5106	5*5109	2*5210	(9) =	559.50

M track length table

.....	1*5107	6*5129	1*5109	1*5210	(9) =	559.50
1*5106	4*5129	1*5108	1*5110	2*5210	(9) =	559.50
.....	8*5129	(8) =	560.00
2*5106	1*5107	1*5129	2*5210	1*5208	(7) =	560.00
2*5106	1*5107	1*5108	1*5109	2*5210	(7) =	560.50
2*5106	2*5129	1*5108	1*5210	(6) =	561.00
2*5106	1*5108	4*5109	1*5110	(8) =	561.50
2*5106	1*5107	1*5129	1*5109	1*5208	(6) =	561.50
2*5106	1*5107	1*5108	2*5109	(6) =	562.00
3*5106	1*5110	(4) =	562.50
1*5106	1*5107	3*5129	2*5109	1*5210	(8) =	563.00
2*5106	1*5129	1*5108	1*5109	1*5110	2*5210	(8) =	563.00
1*5106	5*5129	1*5109	(7) =	563.50
3*5106	1*5210	1*5208	(5) =	564.00
2*5106	1*5129	4*5109	(7) =	564.00
2*5106	1*5129	1*5108	2*5109	1*5110	(7) =	564.50
2*5106	1*5107	1*5129	1*5108	(5) =	565.00
2*5106	2*5129	1*5109	2*5210	(7) =	565.50
1*5106	1*5107	4*5129	1*5210	(7) =	566.00
2*5106	1*5107	3*5109	1*5210	(7) =	566.50
2*5106	2*5129	2*5109	(6) =	567.00
2*5106	2*5129	1*5108	1*5110	(6) =	567.50
2*5106	1*5107	1*5129	3*5210	(7) =	568.00
1*5106	5*5129	1*5110	1*5210	(8) =	568.50
2*5106	2*5129	1*5108	1*5210	1*5208	(7) =	569.00
2*5106	1*5129	3*5109	1*5110	1*5210	(8) =	569.00
2*5106	1*5107	1*5129	1*5109	1*5210	(6) =	569.50
2*5106	3*5129	(5) =	570.00
2*5106	2*5129	1*5110	3*5210	(8) =	570.50
3*5106	1*5110	1*5208	(5) =	570.50
.....	1*5107	6*5129	1*5108	1*5210	(9) =	571.00
2*5106	1*5108	4*5109	2*5210	(9) =	571.00
2*5106	1*5107	2*5109	1*5110	2*5210	(8) =	571.50
3*5106	2*5210	(5) =	572.00
1*5106	1*5107	4*5129	1*5110	(7) =	572.50
2*5106	1*5107	3*5109	1*5110	(7) =	573.00
2*5106	1*5107	1*5129	1*5108	1*5208	(6) =	573.00
3*5106	1*5109	(4) =	573.50
2*5106	1*5129	1*5108	2*5109	2*5210	(8) =	574.00
2*5106	1*5107	1*5129	1*5110	2*5210	(7) =	574.50
1*5106	5*5129	1*5108	(7) =	575.00
2*5106	1*5129	1*5108	3*5109	(7) =	575.50
2*5106	1*5107	1*5129	1*5109	1*5110	(6) =	576.00
2*5106	1*5107	1*5108	1*5109	3*5210	(8) =	576.50
2*5106	2*5129	1*5108	2*5210	(7) =	577.00
1*5106	1*5107	2*5129	5*5109	(9) =	577.50
2*5106	1*5108	4*5109	1*5110	1*5210	(9) =	577.50
.....	1*5107	6*5129	1*5108	1*5110	(9) =	577.50
2*5106	1*5107	1*5129	1*5109	1*5210	1*5208	(7) =	577.50
2*5106	1*5107	1*5108	2*5109	1*5210	(7) =	578.00
2*5106	3*5129	1*5208	(6) =	578.00
3*5106	1*5110	1*5210	(5) =	578.50
1*5106	1*5107	3*5129	2*5109	2*5210	(9) =	579.00
2*5106	1*5129	1*5108	1*5109	1*5110	3*5210	(9) =	579.00
1*5106	5*5129	1*5109	1*5210	(8) =	579.50
3*5106	2*5210	1*5208	(6) =	580.00
.....	1*5107	7*5129	(8) =	580.00
2*5106	1*5129	4*5109	1*5210	(8) =	580.00
2*5106	1*5129	1*5108	2*5109	1*5110	1*5210	(8) =	580.50
1*5106	1*5107	3*5129	3*5109	(8) =	580.50
2*5106	1*5107	1*5129	1*5108	1*5210	(6) =	581.00
2*5106	2*5129	1*5109	3*5210	(8) =	581.50
3*5106	1*5109	1*5208	(5) =	581.50
1*5106	1*5107	4*5129	2*5210	(8) =	582.00
2*5106	1*5107	3*5109	2*5210	(8) =	582.50
2*5106	2*5129	2*5109	1*5210	(7) =	583.00
1*5106	1*5107	4*5129	1*5109	(7) =	583.50
2*5106	2*5129	1*5108	1*5110	1*5210	(7) =	583.50
2*5106	1*5107	4*5109	(7) =	584.00
2*5106	1*5107	1*5108	2*5109	1*5110	(7) =	584.50
3*5106	1*5108	(4) =	585.00
2*5106	1*5107	1*5129	1*5109	2*5210	(7) =	585.50
2*5106	3*5129	1*5210	(6) =	586.00
3*5106	1*5110	1*5210	1*5208	(6) =	586.50
2*5106	1*5129	4*5109	1*5110	(8) =	586.50
2*5106	1*5107	1*5129	2*5109	(6) =	587.00
2*5106	1*5107	1*5129	1*5108	1*5110	(6) =	587.50
3*5106	3*5210	(6) =	588.00
1*5106	1*5107	4*5129	1*5110	1*5210	(8) =	588.50
2*5106	1*5107	1*5129	1*5108	1*5210	1*5208	(7) =	589.00
2*5106	1*5107	3*5109	1*5110	1*5210	(8) =	589.00
3*5106	1*5109	1*5210	(5) =	589.50
2*5106	1*5107	2*5129	(5) =	590.00

M track length table

2*5106	1*5107	1*5129	1*5110	3*5210	(8) =	590.50
1*5106	5*5129	1*5108	1*5210	(8) =	591.00
2*5106	1*5129	1*5108	3*5109	1*5210	(8) =	591.50
2*5106	1*5107	1*5129	1*5109	1*5110	1*5210	(7) =	592.00
2*5106	3*5129	1*5110	(6) =	592.50
3*5106	1*5108	1*5208	(5) =	593.00
2*5106	2*5129	1*5108	3*5210	(8) =	593.00
2*5106	1*5107	1*5129	1*5109	2*5210	1*5208	(8) =	593.50
.....	8*5129	1*5109	(9) =	593.50
2*5106	1*5107	1*5108	2*5109	2*5210	(8) =	594.00
2*5106	3*5129	1*5210	1*5208	(7) =	594.00
3*5106	1*5110	2*5210	(6) =	594.50
1*5106	1*5107	4*5129	1*5108	(7) =	595.00
2*5106	1*5107	1*5108	3*5109	(7) =	595.50
3*5106	1*5109	1*5110	(5) =	596.00
2*5106	1*5129	1*5108	2*5109	1*5110	2*5210	(9) =	596.50
1*5106	1*5107	3*5129	3*5109	1*5210	(9) =	596.50
2*5106	1*5107	1*5129	1*5108	2*5210	(7) =	597.00
3*5106	1*5109	1*5210	1*5208	(6) =	597.50
1*5106	5*5129	1*5108	1*5110	(8) =	597.50
2*5106	1*5129	5*5109	(8) =	597.50
2*5106	1*5107	2*5129	1*5208	(6) =	598.00
2*5106	1*5129	1*5108	3*5109	1*5110	(8) =	598.00
2*5106	1*5107	1*5129	1*5108	1*5109	(6) =	598.50
2*5106	2*5129	2*5109	2*5210	(8) =	599.00
1*5106	1*5107	4*5129	1*5109	1*5210	(8) =	599.50
2*5106	2*5129	1*5108	1*5110	2*5210	(8) =	599.50
1*5106	6*5129	(7) =	600.00
2*5106	2*5129	3*5109	(7) =	600.50
3*5106	1*5108	1*5210	(5) =	601.00
2*5106	1*5107	1*5129	1*5109	3*5210	(8) =	601.50
2*5106	3*5129	2*5210	(7) =	602.00
.....	1*5107	7*5129	1*5110	(9) =	602.50
3*5106	1*5110	2*5210	1*5208	(7) =	602.50
2*5106	1*5129	4*5109	1*5110	1*5210	(9) =	602.50
2*5106	1*5107	1*5129	2*5109	1*5210	(7) =	603.00
2*5106	3*5129	1*5109	(6) =	603.50
3*5106	4*5210	(7) =	604.00
3*5106	1*5109	1*5110	1*5208	(6) =	604.00
1*5106	1*5107	4*5129	1*5110	2*5210	(9) =	604.50
.....	8*5129	1*5108	(9) =	605.00
2*5106	1*5107	1*5129	1*5108	2*5210	1*5208	(8) =	605.00
2*5106	1*5107	3*5109	1*5110	2*5210	(9) =	605.00
3*5106	1*5109	2*5210	(6) =	605.50
2*5106	1*5107	2*5129	1*5210	(6) =	606.00
2*5106	1*5107	4*5109	1*5110	(8) =	606.50
2*5106	1*5107	1*5129	1*5108	1*5109	1*5208	(7) =	606.50
3*5106	2*5109	(5) =	607.00
3*5106	1*5108	1*5110	(5) =	607.50
2*5106	1*5107	1*5129	1*5109	1*5110	2*5210	(8) =	608.00
2*5106	3*5129	1*5110	1*5210	(7) =	608.50
3*5106	1*5108	1*5210	1*5208	(6) =	609.00
2*5106	1*5129	1*5108	4*5109	(8) =	609.00
2*5106	1*5107	1*5129	2*5109	1*5110	(7) =	609.50
3*5106	1*5129	(4) =	610.00
3*5106	1*5110	3*5210	(7) =	610.50
1*5106	1*5107	4*5129	1*5108	1*5210	(8) =	611.00
2*5106	1*5107	1*5108	3*5109	1*5210	(8) =	611.50
2*5106	3*5129	1*5109	1*5208	(7) =	611.50
3*5106	1*5109	1*5110	1*5210	(6) =	612.00
2*5106	1*5107	2*5129	1*5110	(6) =	612.50
2*5106	1*5107	1*5129	1*5108	3*5210	(8) =	613.00
3*5106	1*5109	2*5210	1*5208	(7) =	613.50
2*5106	1*5129	5*5109	1*5210	(9) =	613.50
.....	1*5107	7*5129	1*5109	(9) =	613.50
1*5106	5*5129	1*5108	1*5110	1*5210	(9) =	613.50
1*5106	1*5107	3*5129	4*5109	(9) =	614.00
2*5106	1*5107	2*5129	1*5210	1*5208	(7) =	614.00
2*5106	1*5129	1*5108	3*5109	1*5110	1*5210	(9) =	614.00
2*5106	1*5107	1*5129	1*5108	1*5109	1*5210	(7) =	614.50
2*5106	3*5129	1*5108	(6) =	615.00
3*5106	1*5108	1*5110	1*5208	(6) =	615.50
1*5106	1*5107	4*5129	1*5109	2*5210	(9) =	615.50
2*5106	2*5129	1*5108	1*5110	3*5210	(9) =	615.50
1*5106	6*5129	1*5210	(8) =	616.00
2*5106	2*5129	3*5109	1*5210	(8) =	616.50
3*5106	1*5108	2*5210	(6) =	617.00
2*5106	1*5107	5*5109	(8) =	617.50
1*5106	1*5107	4*5129	1*5108	1*5110	(8) =	617.50
3*5106	1*5129	1*5208	(5) =	618.00
2*5106	1*5107	1*5108	3*5109	1*5110	(8) =	618.00
2*5106	3*5129	3*5210	(8) =	618.00
3*5106	1*5108	1*5109	(5) =	618.50

M track length table

2*5106	1*5107	1*5129	2*5109	2*5210	(8) =	619.00
2*5106	3*5129	1*5109	1*5210	(7) =	619.50
1*5106	1*5107	5*5129	(7) =	620.00
2*5106	1*5107	1*5129	3*5109	(7) =	620.50
2*5106	1*5107	1*5129	1*5108	1*5109	1*5110	(7) =	621.00
3*5106	1*5109	3*5210	(7) =	621.50
2*5106	1*5107	2*5129	2*5210	(7) =	622.00
1*5106	6*5129	1*5110	(8) =	622.50
3*5106	2*5109	1*5210	(6) =	623.00
3*5106	1*5108	1*5110	1*5210	(6) =	623.50
2*5106	1*5107	2*5129	1*5109	(6) =	623.50
2*5106	1*5107	1*5129	1*5109	1*5110	3*5210	(9) =	624.00
2*5106	3*5129	1*5110	2*5210	(8) =	624.50
3*5106	1*5108	2*5210	1*5208	(7) =	625.00
.....	1*5107	7*5129	1*5108	(9) =	625.00
2*5106	1*5129	1*5108	4*5109	1*5210	(9) =	625.00
2*5106	1*5107	1*5129	2*5109	1*5110	1*5210	(8) =	625.50
3*5106	1*5129	1*5210	(5) =	626.00
3*5106	1*5110	4*5210	(8) =	626.50
3*5106	1*5108	1*5109	1*5208	(6) =	626.50
1*5106	1*5107	4*5129	1*5108	2*5210	(9) =	627.00
2*5106	1*5107	1*5108	3*5109	2*5210	(9) =	627.50
2*5106	3*5129	1*5109	1*5210	1*5208	(8) =	627.50
3*5106	1*5109	1*5110	2*5210	(7) =	628.00
2*5106	1*5107	2*5129	1*5110	1*5210	(7) =	628.50
2*5106	1*5107	1*5108	4*5109	(8) =	629.00
3*5106	2*5109	1*5110	(6) =	629.50
3*5106	1*5107	(4) =	630.00
2*5106	1*5107	1*5129	1*5108	1*5109	2*5210	(8) =	630.50
2*5106	3*5129	1*5108	1*5210	(7) =	631.00
3*5106	1*5108	1*5110	1*5210	1*5208	(7) =	631.50
2*5106	1*5129	1*5108	4*5109	1*5110	(9) =	631.50
2*5106	1*5107	2*5129	1*5109	1*5208	(7) =	631.50
2*5106	1*5107	1*5129	1*5108	2*5109	(7) =	632.00
3*5106	1*5129	1*5110	(5) =	632.50
3*5106	1*5108	3*5210	(7) =	633.00
1*5106	6*5129	1*5109	(8) =	633.50
3*5106	1*5129	1*5210	1*5208	(6) =	634.00
2*5106	2*5129	4*5109	(8) =	634.00
3*5106	1*5108	1*5109	1*5210	(6) =	634.50
2*5106	1*5107	2*5129	1*5108	(6) =	635.00
2*5106	3*5129	1*5109	2*5210	(8) =	635.50
1*5106	1*5107	5*5129	1*5210	(8) =	636.00
2*5106	1*5107	1*5129	3*5109	1*5210	(8) =	636.50
2*5106	3*5129	2*5109	(7) =	637.00
2*5106	3*5129	1*5108	1*5110	(7) =	637.50
2*5106	1*5107	2*5129	3*5210	(8) =	638.00
3*5106	1*5107	1*5208	(5) =	638.00
1*5106	6*5129	1*5110	1*5210	(9) =	638.50
3*5106	2*5109	2*5210	(7) =	639.00
3*5106	1*5108	1*5110	2*5210	(7) =	639.50
2*5106	1*5107	2*5129	1*5109	1*5210	(7) =	639.50
2*5106	4*5129	(6) =	640.00
3*5106	3*5109	(6) =	640.50
3*5106	1*5108	1*5109	1*5110	(6) =	641.00
2*5106	1*5107	1*5129	2*5109	1*5110	2*5210	(9) =	641.50
3*5106	1*5129	2*5210	(6) =	642.00
3*5106	1*5108	1*5109	1*5210	1*5208	(7) =	642.50
1*5106	1*5107	5*5129	1*5110	(8) =	642.50
2*5106	1*5107	1*5129	3*5109	1*5110	(8) =	643.00
2*5106	1*5107	2*5129	1*5108	1*5208	(7) =	643.00
3*5106	1*5129	1*5109	(5) =	643.50
3*5106	1*5109	1*5110	3*5210	(8) =	644.00
2*5106	1*5107	2*5129	1*5110	2*5210	(8) =	644.50
1*5106	6*5129	1*5108	(8) =	645.00
3*5106	2*5109	1*5110	1*5210	(7) =	645.50
3*5106	1*5107	1*5210	(5) =	646.00
2*5106	1*5107	1*5129	1*5108	1*5109	3*5210	(9) =	646.50
2*5106	3*5129	1*5108	2*5210	(8) =	647.00
3*5106	1*5108	1*5110	2*5210	1*5208	(8) =	647.50
2*5106	1*5107	2*5129	1*5109	1*5210	1*5208	(8) =	647.50
2*5106	1*5129	1*5108	4*5109	1*5110	1*5210	(10) =	647.50
.....	1*5107	7*5129	1*5108	1*5110	(10) =	647.50
1*5106	1*5107	3*5129	5*5109	(10) =	647.50
2*5106	1*5107	1*5129	1*5108	2*5109	1*5210	(8) =	648.00
2*5106	4*5129	1*5208	(7) =	648.00
3*5106	1*5129	1*5110	1*5210	(6) =	648.50
3*5106	1*5108	4*5210	(8) =	649.00
3*5106	1*5108	1*5109	1*5110	1*5208	(7) =	649.00
1*5106	6*5129	1*5109	1*5210	(9) =	649.50
3*5106	1*5129	2*5210	1*5208	(7) =	650.00
.....	1*5107	8*5129	(9) =	650.00
2*5106	2*5129	4*5109	1*5210	(9) =	650.00

M track length table

3*5106	1*5108	1*5109	2*5210	(7) =	650.50
2*5106	1*5107	2*5129	1*5108	1*5210	(7) =	651.00
2*5106	1*5107	1*5108	4*5109	1*5110	(9) =	651.50
2*5106	3*5129	1*5109	3*5210	(9) =	651.50
3*5106	1*5129	1*5109	1*5208	(6) =	651.50
3*5106	1*5108	2*5109	(6) =	652.00
3*5106	1*5107	1*5110	(5) =	652.50
2*5106	3*5129	2*5109	1*5210	(8) =	653.00
1*5106	1*5107	1*5129	1*5109	(8) =	653.50
2*5106	3*5129	1*5108	1*5110	1*5210	(8) =	653.50
2*5106	1*5107	1*5129	4*5109	(8) =	654.00
3*5106	1*5107	1*5210	1*5208	(6) =	654.00
2*5106	1*5107	1*5129	1*5108	2*5109	1*5110	(8) =	654.50
3*5106	1*5129	1*5108	(5) =	655.00
2*5106	1*5107	2*5129	1*5109	2*5210	(8) =	655.50
3*5106	1*5108	1*5110	3*5210	(8) =	655.50
2*5106	4*5129	1*5210	(7) =	656.00
3*5106	3*5109	1*5210	(7) =	656.50
2*5106	1*5107	2*5129	2*5109	(7) =	657.00
3*5106	1*5108	1*5109	1*5110	1*5210	(7) =	657.00
2*5106	1*5107	2*5129	1*5108	1*5110	(7) =	657.50
3*5106	1*5129	3*5210	(7) =	658.00
3*5106	1*5108	1*5109	2*5210	1*5208	(8) =	658.50
1*5106	1*5107	5*5129	1*5110	1*5210	(9) =	658.50
2*5106	1*5107	1*5129	3*5109	1*5110	1*5210	(9) =	659.00
2*5106	1*5107	2*5129	1*5108	1*5210	1*5208	(8) =	659.00
3*5106	1*5129	1*5109	1*5210	(6) =	659.50
2*5106	1*5107	3*5129	(6) =	660.00
3*5106	1*5107	1*5110	1*5208	(6) =	660.50
2*5106	1*5107	2*5129	1*5110	3*5210	(9) =	660.50
1*5106	6*5129	1*5108	1*5210	(9) =	661.00
3*5106	2*5109	1*5110	2*5210	(8) =	661.50
3*5106	1*5107	2*5210	(6) =	662.00
2*5106	4*5129	1*5110	(7) =	662.50
3*5106	1*5129	1*5108	1*5208	(6) =	663.00
3*5106	3*5109	1*5110	(7) =	663.00
3*5106	1*5107	1*5109	(5) =	663.50
2*5106	1*5107	1*5129	1*5108	2*5109	2*5210	(9) =	664.00
2*5106	4*5129	1*5210	1*5208	(8) =	664.00
3*5106	1*5129	1*5110	2*5210	(7) =	664.50
1*5106	1*5107	5*5129	1*5108	(8) =	665.00
2*5106	1*5107	1*5129	1*5108	3*5109	(8) =	665.50
3*5106	1*5129	1*5109	1*5110	(6) =	666.00
3*5106	1*5108	1*5109	3*5210	(8) =	666.50
2*5106	1*5107	2*5129	1*5108	2*5210	(8) =	667.00
3*5106	1*5129	1*5109	1*5210	1*5208	(7) =	667.50
1*5106	6*5129	1*5108	1*5110	(9) =	667.50
2*5106	2*5129	5*5109	(9) =	667.50
3*5106	1*5108	2*5109	1*5210	(7) =	668.00
3*5106	1*5107	1*5110	1*5210	(6) =	668.50
2*5106	3*5129	2*5109	2*5210	(9) =	669.00
2*5106	3*5129	1*5108	1*5110	2*5210	(9) =	669.50
1*5106	1*5107	5*5129	1*5109	1*5210	(9) =	669.50
3*5106	1*5107	2*5210	1*5208	(7) =	670.00
1*5106	7*5129	(8) =	670.00
2*5106	3*5129	3*5109	(8) =	670.50
3*5106	1*5129	1*5108	1*5210	(6) =	671.00
3*5106	1*5108	1*5110	4*5210	(9) =	671.50
2*5106	1*5107	2*5129	1*5109	3*5210	(9) =	671.50
3*5106	1*5107	1*5109	1*5208	(6) =	671.50
2*5106	4*5129	2*5210	(8) =	672.00
3*5106	3*5109	2*5210	(8) =	672.50
2*5106	1*5107	2*5129	2*5109	1*5210	(8) =	673.00
3*5106	1*5108	1*5109	1*5110	2*5210	(8) =	673.00
2*5106	4*5129	1*5109	(7) =	673.50
3*5106	4*5109	(7) =	674.00
3*5106	1*5108	2*5109	1*5110	(7) =	674.50
3*5106	1*5107	1*5108	(5) =	675.00
3*5106	1*5129	1*5109	2*5210	(7) =	675.50
2*5106	1*5107	3*5129	1*5210	(7) =	676.00
2*5106	1*5107	1*5129	4*5109	1*5110	(9) =	676.50
3*5106	1*5107	1*5110	1*5210	1*5208	(7) =	676.50
3*5106	1*5129	2*5109	(6) =	677.00
3*5106	1*5129	1*5108	1*5110	(6) =	677.50
3*5106	1*5107	3*5210	(7) =	678.00
2*5106	4*5129	1*5110	1*5210	(8) =	678.50
3*5106	1*5129	1*5108	1*5210	1*5208	(7) =	679.00
3*5106	3*5109	1*5110	1*5210	(8) =	679.00
3*5106	1*5107	1*5109	1*5210	(6) =	679.50
3*5106	2*5129	(5) =	680.00
3*5106	1*5129	1*5110	3*5210	(8) =	680.50
1*5106	1*5107	5*5129	1*5108	1*5210	(9) =	681.00
2*5106	1*5107	1*5129	1*5108	3*5109	1*5210	(9) =	681.50

M track length table

2*5106	4*5129	1*5109	1*5208	(8) =	681.50
3*5106	1*5129	1*5109	1*5110	1*5210	(7) =	682.00
2*5106	1*5107	3*5129	1*5110	(7) =	682.50
3*5106	1*5107	1*5108	1*5208	(6) =	683.00
2*5106	1*5107	2*5129	1*5108	3*5210	(9) =	683.00
3*5106	1*5129	1*5109	2*5210	1*5208	(8) =	683.50
2*5106	2*5129	5*5109	1*5210	(10) =	683.50
.....	1*5107	8*5129	1*5109	(10) =	683.50
1*5106	6*5129	1*5108	1*5110	1*5210	(10) =	683.50
3*5106	1*5108	2*5109	2*5210	(8) =	684.00
3*5106	1*5107	1*5110	2*5210	(7) =	684.50
2*5106	4*5129	1*5108	(7) =	685.00
3*5106	1*5108	3*5109	(7) =	685.50
3*5106	1*5107	1*5109	1*5110	(6) =	686.00
2*5106	3*5129	3*5109	1*5210	(9) =	686.50
3*5106	1*5129	1*5108	2*5210	(7) =	687.00
2*5106	1*5107	1*5129	5*5109	(9) =	687.50
3*5106	1*5107	1*5109	1*5210	1*5208	(7) =	687.50
1*5106	1*5107	5*5129	1*5108	1*5110	(9) =	687.50
3*5106	2*5129	1*5208	(6) =	688.00
2*5106	1*5107	1*5129	1*5108	3*5109	1*5110	(9) =	688.00
2*5106	4*5129	3*5210	(9) =	688.00
3*5106	1*5129	1*5108	1*5109	(6) =	688.50
3*5106	1*5108	1*5109	1*5110	3*5210	(9) =	689.00
2*5106	1*5107	2*5129	2*5109	2*5210	(9) =	689.00
2*5106	4*5129	1*5109	1*5210	(8) =	689.50
1*5106	1*5107	6*5129	(8) =	690.00
3*5106	4*5109	1*5210	(8) =	690.00
2*5106	1*5107	2*5129	3*5109	(8) =	690.50
3*5106	1*5108	2*5109	1*5110	1*5210	(8) =	690.50
3*5106	1*5107	1*5108	1*5210	(6) =	691.00
3*5106	1*5129	1*5109	3*5210	(8) =	691.50
2*5106	1*5107	3*5129	2*5210	(8) =	692.00
3*5106	1*5107	1*5110	2*5210	1*5208	(8) =	692.50
1*5106	7*5129	1*5110	(9) =	692.50
3*5106	1*5129	2*5109	1*5210	(7) =	693.00
2*5106	1*5107	3*5129	1*5109	(7) =	693.50
3*5106	1*5129	1*5108	1*5110	1*5210	(7) =	693.50
3*5106	1*5107	4*5210	(8) =	694.00
3*5106	1*5107	1*5109	1*5110	1*5208	(7) =	694.00
2*5106	4*5129	1*5110	2*5210	(9) =	694.50
3*5106	3*5109	1*5110	2*5210	(9) =	695.00
3*5106	1*5129	1*5108	2*5210	1*5208	(8) =	695.00
3*5106	1*5107	1*5109	2*5210	(7) =	695.50
3*5106	2*5129	1*5210	(6) =	696.00
3*5106	1*5129	1*5108	1*5109	1*5208	(7) =	696.50
3*5106	4*5109	1*5110	(8) =	696.50
3*5106	1*5107	2*5109	(6) =	697.00
3*5106	1*5107	1*5108	1*5110	(6) =	697.50
3*5106	1*5129	1*5109	1*5110	2*5210	(8) =	698.00
2*5106	1*5107	3*5129	1*5110	1*5210	(8) =	698.50
2*5106	1*5107	1*5129	1*5108	4*5109	(9) =	699.00
3*5106	1*5107	1*5108	1*5210	1*5208	(7) =	699.00
3*5106	1*5129	2*5109	1*5110	(7) =	699.50
3*5106	1*5107	1*5129	(5) =	700.00
3*5106	1*5107	1*5110	3*5210	(8) =	700.50
2*5106	4*5129	1*5108	1*5210	(8) =	701.00
3*5106	1*5108	3*5109	1*5210	(8) =	701.50
3*5106	1*5107	1*5109	1*5110	1*5210	(7) =	702.00
3*5106	2*5129	1*5110	(6) =	702.50
3*5106	1*5129	1*5108	3*5210	(8) =	703.00
1*5106	7*5129	1*5109	(9) =	703.50
3*5106	1*5107	1*5109	2*5210	1*5208	(8) =	703.50
2*5106	3*5129	4*5109	(9) =	704.00
3*5106	2*5129	1*5210	1*5208	(7) =	704.00
3*5106	1*5129	1*5108	1*5109	1*5210	(7) =	704.50
2*5106	1*5107	3*5129	1*5108	(7) =	705.00
3*5106	1*5107	1*5108	1*5110	1*5208	(7) =	705.50
2*5106	4*5129	1*5109	2*5210	(9) =	705.50
3*5106	4*5109	2*5210	(9) =	706.00
1*5106	1*5107	6*5129	1*5210	(9) =	706.00
2*5106	1*5107	2*5129	3*5109	1*5210	(9) =	706.50
3*5106	1*5108	2*5109	1*5110	2*5210	(9) =	706.50
3*5106	1*5107	1*5108	2*5210	(7) =	707.00
3*5106	5*5109	(8) =	707.50
2*5106	4*5129	1*5108	1*5110	(8) =	707.50
3*5106	1*5108	3*5109	1*5110	(8) =	708.00
3*5106	1*5107	1*5129	1*5208	(6) =	708.00
3*5106	1*5107	1*5108	1*5109	(6) =	708.50
3*5106	1*5129	2*5109	2*5210	(8) =	709.00
2*5106	1*5107	3*5129	1*5109	1*5210	(8) =	709.50
3*5106	1*5129	1*5108	1*5110	2*5210	(8) =	709.50
2*5106	5*5129	(7) =	710.00

M track length table

3*5106	1*5129	3*5109	(7) =	710.50
3*5106	1*5129	1*5108	1*5109	1*5110	(7) =	711.00
3*5106	1*5107	1*5109	3*5210	(8) =	711.50
3*5106	2*5129	2*5210	(7) =	712.00
1*5106	1*5107	6*5129	1*5110	(9) =	712.50
3*5106	4*5109	1*5110	1*5210	(9) =	712.50
3*5106	1*5129	1*5108	1*5109	1*5210	1*5208 (8) =	712.50
3*5106	1*5107	2*5109	1*5210	(7) =	713.00
3*5106	2*5129	1*5109	(6) =	713.50
3*5106	1*5129	1*5109	1*5110	3*5210	(9) =	714.00
2*5106	1*5107	3*5129	1*5110	2*5210	(9) =	714.50
1*5106	7*5129	1*5108	(9) =	715.00
3*5106	1*5107	1*5108	2*5210	1*5208 (8) =	715.00
3*5106	1*5129	2*5109	1*5110	1*5210	(8) =	715.50
3*5106	1*5107	1*5129	1*5210	(6) =	716.00
3*5106	1*5107	1*5108	1*5109	1*5208	(7) =	716.50
3*5106	1*5107	1*5110	4*5210	(9) =	716.50
2*5106	4*5129	1*5108	2*5210	(9) =	717.00
3*5106	1*5108	3*5109	2*5210	(9) =	717.50
3*5106	1*5107	1*5109	1*5110	2*5210	(8) =	718.00
3*5106	2*5129	1*5110	1*5210	(7) =	718.50
3*5106	1*5108	4*5109	(8) =	719.00
3*5106	1*5107	2*5109	1*5110	(7) =	719.50
4*5106	(4) =	720.00

lengths that cannot be filled:

0.5	1.0	1.5	2.0	2.5	3.0	3.5	4.0	4.5	5.0	5.5	6.0	6.5	7.0
7.5	8.5	9.0	9.5	10.0	10.5	11.0	11.5	12.0	12.5	13.0	13.5	14.0	14.5
15.0	15.5	16.5	17.0	17.5	18.0	18.5	19.0	19.5	20.0	20.5	21.0	21.5	22.0
23.0	23.5	24.5	25.0	25.5	26.0	26.5	27.0	27.5	28.0	28.5	29.0	29.5	30.0
31.0	31.5	32.5	33.0	34.0	34.5	35.0	35.5	36.0	36.5	37.0	37.5	38.0	39.0
39.5	40.5	41.0	42.0	42.5	43.0	43.5	44.0	44.5	45.5	46.0	47.0	47.5	48.5
49.0	50.0	50.5	51.0	51.5	52.0	52.5	53.5	54.0	55.0	55.5	56.5	57.0	58.0
58.5	59.0	59.5	60.0	60.5	61.5	62.0	63.0	63.5	64.5	65.0	66.0	66.5	68.0
68.5	69.5	71.0	71.5	72.5	73.0	74.0	74.5	76.0	76.5	77.5	79.0	79.5	80.5
81.0	82.0	82.5	84.0	84.5	85.5	87.0	87.5	88.5	89.0	90.5	92.0	93.5	95.0
95.5	96.5	97.0	98.5										

100.0	101.5	103.0	104.5	105.0	106.5	108.0	109.5	111.0	113.0	114.5	116.0	117.5	119.0
121.0	122.5	124.0	125.5	127.0	129.0	130.5	132.0	133.5	138.5	141.5	146.5	149.5	154.5